

DAFTAR ISI

HALAMAN JUDUL.....	1
LEMBAR PERSOALAN	i
LEMBAR PENGESAHAN	ii
LEMBAR PERNYATAAN	iii
MOTTO	iv
KATA PENGANTAR	v
INTI SARI.....	vii
ABSTRACT	viii
DAFTAR ISI.....	ix
DAFTAR GAMBAR	xi
DAFTAR TABEL	xiii
DAFTAR LAMPIRAN	xiv
BAB I PENDAHULUAN	1
1.1 Latar Belakang	1
1.2 Rumusan Masalah	2
1.3 Tujuan Penelitian.....	2
1.4 Batasan Masalah	2
1.5 Metode Pengumpulan Data	2
1.6 Sistematika Penulisan.....	3
BAB II TINJAUAN PUSTAKA DAN DASAR TEORI.....	5
2.1 <i>Top Drive</i>	5
2.2 Mesin Diesel.....	5
2.3 <i>Maintenance Diesel Engine</i> DDC/MTU	24
2.4 Program Analisa Pelumas	26
2.5 Identifikasi Mechanical Failure	28
BAB III METODE PENELITIAN.....	35
3.1 Diagram Alir Penelitian.....	35
3.2 Tempat dan Waktu Penelitian	37
3.3 Bahan dan Alat Penelitian	37
3.4 Deskripsi Kerusakan.....	38
3.5 Prosedur Pengambilan Data	39

BAB IV DATA HASIL DAN PEMBAHASAN	42
4.1 Hasil Pengumpulan data Histori <i>Maintenance</i>	42
4.2 Hasil Program Analisis Pelumas	44
4.3 <i>Engine Overhaul</i>	46
4.3.1 <i>Engine Block</i>	47
4.3.2 <i>Connecting Rod Journal</i>	47
4.3.3 <i>Connecting Rod</i>	48
4.3.4 <i>Bearing Shell</i>	48
4.3.5 <i>Connecting Rod Bolt and Spacer</i>	49
4.4 Analisis Kerusakan Mesin	49
4.4.1 Analisis <i>Maintenance Histoiy</i> dan PAP	49
4.4.2 Idetiflkasi <i>Mechanical Failure</i>	50
4.5 <i>Root Cause Analysis</i>	52
BAB V PENUTUP	55
5.1 Kesimpulan	55
5.2 Saran	55
DAFTAR PUSTAKA	57
LAMPIRAN	58

DAFTAR GAMBAR

Gambar 2.1 <i>Top Drive Tesco HCI 500 ton</i>	5
Gambar 2.2 <i>Engine Block</i>	6
Gambar 2.3 <i>Cylinder Head</i>	7
Gambar 2.4 <i>Cylinder Head</i>	8
Gambar 2.5 <i>Timing Valve Assembly</i>	9
Gambar 2.6 <i>Crank Shaft</i>	11
Gambar 2.7 <i>Crank Shaft Main Bearing Shells</i>	12
Gambar 2.8 <i>Crankshaft 16v2000</i>	12
Gambar 2.9 <i>Piston and Piston Rings</i>	14
Gambar 2.10 <i>Piston and Ring Piston Assembly</i>	14
Gambar 2.11 <i>Connecting Rod Assembly</i>	15
Gambar 2.12 <i>Cylinder Liner</i>	16
Gambar 2.13 <i>Element Cylinder Liner</i>	16
Gambar 2.14 <i>Cam Shaft and Bearings</i>	17
Gambar 2.15 <i>Mesin Diesel 2 Langkah</i>	19
Gambar 2.16 <i>ECM DDC 16V2000</i>	20
Gambar 2.17 <i>Nexiq DDEC Pro-Link iQ</i>	21
Gambar 2.18 <i>DDEC 1</i>	22
Gambar 2.19 <i>DDEC II</i>	23
Gambar 2.20 <i>DDEC III</i>	24
Gambar 2.22 <i>Inisiasi Retakan</i>	29
Gambar 2.23 <i>Retak Belah</i>	30
Gambar 2.24 <i>Retak Belah lainnya</i>	30
Gambar 2.25 <i>Beach Mark</i>	31
Gambar 2.26 <i>Thread Failure</i>	32
Gambar 2.27 <i>Inisiasi crack</i>	33
Gambar 3.1 <i>Flow Chart</i>	36
Gambar 3.2 <i>Mesin Diesel Detroit Series 16V2000</i>	37
Gambar 3.3 <i>Kerusakan Mesin</i>	38
Gambar 3.4 <i>ECM Reader (a) Prosedur Instalasi (b) DDEC</i>	39

Gambar 3.5 <i>Manual Book Detroit Series 16V2000</i>	40
Gambar 4.1 DDEC.....	42
Gambar 4.2 Grafik <i>Wear Trending</i>	46
Gambar 4.3 Kondisi Komponen Mesin.....	47
Gambar 4.4 <i>Connecting Rod Journal</i>	48
Gambar 4.5 Kondisi Batang Penghubung	48
Gambar 4.6 <i>Bearing Shell Condition</i>	48
Gambar 4.7 Kondisi Baut Batang Penghubung.....	49
Gambar 4.9 <i>Mechanical Failur Identification</i>	50
Gambar 4.10 <i>Bolt A Mechanical Failure Identification</i>	51
Gambar 4.11 <i>Bolt B Mechanical Failure Identification</i>	51
Gambar 4.12 <i>Fatigue Fracture join area</i>	52
Gambar 4.13 <i>Root Cause Analysis</i>	53

DAFTAR TABEL

Tabel 4.1 Histori penambahan oli dan <i>Coolant Engine</i>	43
Tabel 4.2 <i>Daily Filter Cut</i>	44
Tabel 4.3 Program Analisa Pelumas	45
Tabel 4.4 Analisis fenomena temuan kerusakan	53

DAFTAR LAMPIRAN

Lampiran 1 Program Analisa Pelumas	58
Lampiran 2 Detroit <i>Diesel Engine</i> 16V2000	59
Lampiran 3 <i>Overhaul Activity</i>	60
Lampiran 4 DDEC	61