

## DAFTAR ISI

LEMBAR PENGESAHAN.....	ii
LEMBAR PENGESAHAN.....	iii
SURAT BEBAS PLAGIASI.....	iv
SURAT PERNYATAAN KEBENARAN DOKUMEN.....	v
MOTTO.....	vi
LEMBAR PERESEMBAHAN.....	vii
KATA PENGANTAR.....	viii
DAFTAR ISI.....	x
DAFTAR GAMBAR.....	xiii
DAFTAR TABEL.....	xv
ABSTRAK.....	xvi
ABSTRACT.....	xvii
BAB I PENDAHULUAN.....	1
1.1 Latar Belakang.....	1
1.2 Rumusan Masalah.....	5
1.3 Tujuan Penelitian.....	5
1.4 Batasan Masalah.....	6
1.5 Manfaat Penelitian.....	6
1.6 Sistematika Penelitian.....	7
BAB II LANDASAN TEORI.....	9
2.1 Tinjauan Pustaka.....	9
2.2 Unit <i>Drilling</i> .....	11
2.2.1 Furukawa HCR 1500 D20.....	12
2.3 <i>Engine Diesel</i> .....	14
2.3.1 <i>Engine C – 9</i> .....	16
2.4 Komponen Utama Mesin Diesel.....	17
2.4.1 <i>Cylinder Block</i> .....	17
2.4.2 Silinder Liner.....	18
2.4.3 <i>Head Cylinder</i> .....	18

2.4.4	<i>Camshaft</i> .....	18
2.4.5	<i>Crankshaft</i> .....	19
2.4.6	<i>Piston</i> .....	19
2.5	<i>Sistem Pada Mesin Diesel</i> .....	19
2.5.1	<i>Lubrication System</i> .....	20
2.5.2	<i>Cooling System</i> .....	21
2.5.3	<i>Fuel System</i> .....	22
2.5.4	<i>Air Intake and Exhaust System</i> .....	24
2.5.5	<i>Sistem Starter</i> .....	25
2.5.6	<i>Sistem Charging</i> .....	26
2.6	<i>Hydrailuc Electronic Unit Injector (HEUI)</i> .....	27
2.	<i>Electronic Control Module</i> .....	29
3.	<i>Unit Injector Hydrailuc Pump</i> .....	29
4.	<i>Fuel Transfer Pump</i> .....	29
5.	<i>Injection Actuation Pressure Sensor (IAP)</i> .....	30
2.6.1	<i>Low Pressure Fuel System</i> .....	30
2.6.2	<i>Injection Actuation System</i> .....	31
2.6.3	<i>Actuation Oil Pressure Control</i> .....	33
2.6.4	<i>HEUI Injector</i> .....	33
2.7	<i>Scheduled Oil Sampling (SOS)</i> .....	35
2.8	<i>Fuel dilution</i> .....	38
2.9	<i>Maintenance</i> .....	40
2.9.1	<i>Preventive Maintenance</i> .....	40
2.9.2	<i>Corrective Maintenance (Unshceduled)</i> .....	42
2.10	<i>Root cause Analysis (RCA)</i> .....	43
2.10.1	<i>5 Why Analysis</i> .....	44
2.10.2	<i>Fishbone Diagram</i> .....	45
BAB III	<b>METODOLOGI PENELITIAN</b> .....	47
3.1	<i>Lokasi dan Waktu Penelitian</i> .....	47
3.2	<i>Objek Penelitian</i> .....	47
3.3	<i>Alat dan Software Penelitian</i> .....	47

3.4 Data.....	49
3.4.1 Data primer .....	49
3.4.2 Data Sekunder .....	51
3.5 Diagram Alir.....	51
3.6 Metodologi Penelitian .....	52
3.6.1 Identifikasi Masalah.....	53
3.6.2 Studi Literatur .....	53
3.6.3 Pengambilan Data .....	54
3.6.4 Pengolahan Data .....	58
3.6.5 Analisis Data.....	58
3.6.6 Kesimpulan dan Saran .....	60
<b>BAB IV HASIL DAN PEMBAHASAN .....</b>	<b>61</b>
4.1 Identifikasi Data .....	61
4.1.1 Identifikasi Data <i>Component Replacement</i> .....	61
4.1.2 Identifikasi Data <i>Periodic Service</i> .....	63
4.1.3 Identifikasi Data <i>Historical Breakdown</i> .....	64
4.1.4 Identifikasi Data <i>Fluid Top Up</i> .....	66
4.1.5 Identifikasi Data <i>Filter Cut</i> .....	67
4.1.6 Identifikasi Data Hasil <i>Scheduled Oil Sampling (SOS)</i> .....	68
4.1.7 Identifikasi Data Status .....	84
4.1.8 Identifikasi Data <i>Product Support Report (PSRPT)</i> .....	86
4.1.9 Identifikasi Data Hasil Uji <i>Cutout Injector Test</i> .....	87
4.1.10 Identifikasi Hasil Uji <i>Leak Test</i> .....	89
4.2 Analisis Data .....	91
4.2.1 Analisis Data SOS dan Kondisi <i>Engine</i> .....	91
4.2.2 Analisis <i>Root cause</i> .....	94
4.2.3 Analisis <i>Corrective Action</i> dan Rumusan <i>Predicive Action</i> .....	101
<b>BAB V PENUTUP .....</b>	<b>105</b>
5.1 Kesimpulan.....	105
5.2 Saran .....	106
<b>LAMPIRAN .....</b>	<b>113</b>

## DAFTAR GAMBAR

Gambar 1.1 Jumlah Kegagalan Unit Furukawa HCR 1500 .....	2
Gambar 1.2 Durasi <i>Breakdown</i> Unit Furukawa HCR 1500.....	2
Gambar 1.3 Top Rataan Waktu <i>Downtime</i> .....	3
Gambar 2.1 Furukawa HCR 1500 D20 .....	12
Gambar 2.2 Dimensi Furukawa HCR 1500 D20 .....	13
Gambar 2.3 <i>Engine C - 9</i> .....	17
Gambar 2.4 Skematik HEUI .....	23
Gambar 2.5 HEUI .....	28
Gambar 2.6 <i>Injector Hydrailuc Pump</i> .....	29
Gambar 2.7 <i>Low Pressure</i> HEUI .....	30
Gambar 2.8 <i>Actuation Oil Flow</i> .....	32
Gambar 2.9 Bagian – Bagian <i>Injector</i> HEUI .....	34
Gambar 2.10 <i>5 Why Analysis</i> .....	44
Gambar 2.11 Diagram Fishbone .....	46
Gambar 3.1 Diagram Alir.....	52
Gambar 3.2 <i>Worksheet 5 Why Analysis</i> .....	59
Gambar 4.1 Aktivitas <i>Periodic Service</i> .....	63
Gambar 4.2 Riwayat <i>Periodic Service</i> .....	64
Gambar 4.3 <i>Historical Engine Oil Top Up</i> .....	67
Gambar 4.4 <i>Filter Cut</i> .....	68
Gambar 4.5 Grafik SOS Kandungan <i>Wear metal</i> .....	70
Gambar 4.6 Graifk Hasil SOS PQI .....	72
Gambar 4.7 Tren Grafik Hasil SOS Kandungan <i>Contaminants</i> .....	74
Gambar 4.8 Hasil SOS Komponen <i>Additives</i> .....	76
Gambar 4.9 Grafik Hasil SOS <i>Oil Condition</i> .....	79
Gambar 4.10 Grafik SOS <i>Percentage of Fuel</i> .....	80
Gambar 4.11 Grafik Hasil SOS <i>Total Base Number</i> .....	82
Gambar 4.12 Grafik Hasil SOS V100.....	84
Gambar 4.13 Data <i>Status Engine C9</i> .....	85
Gambar 4.14 Data <i>Product Support Report (PSRPT)</i> .....	86
Gambar 4.15 Hasil Uji <i>Cutout Injector</i> 21 Juni 2024 .....	88
Gambar 4.16 Hasil Uji <i>Cutout Injector</i> 10 Desember 2024.....	88
Gambar 4.17 Hasil Uji <i>Leak Test</i> .....	89
Gambar 4.18 <i>Seal Injector</i> .....	89
Gambar 4.19 Bearing .....	92
Gambar 4.20 <i>Fishbone Diagram</i> .....	95



Gambar 4.21 Analisis 5 <i>Why</i> .....	98
Gambar 4.22 <i>Head Cylinder</i> Cat C9 .....	100
Gambar 4.23 HEUI <i>Pump Assambly</i> .....	102

## DAFTAR TABEL

Tabel 2.1 Spesifikasi HCR 1500 D20 .....	14
Tabel 2.2 Spesifikasi <i>Engine Cat C9</i> .....	16
Tabel 4.1 Data <i>History Component Replacement</i> .....	61
Tabel 4.2 Data <i>Historical Breakdown</i> .....	65
Tabel 4.3 Klasifikasi Filter Cut .....	67
Tabel 4.4 Hasil <i>Scheduled Oil Sampling Wear metal</i> .....	69
Tabel 4.5 Hasil SOS PQI .....	71
Tabel 4.6 Hasil SOS Terhadap Kandungan <i>Contaminants</i> .....	73
Tabel 4.7 Hasil SOS <i>Additives</i> .....	75
Tabel 4.8 Hasil SOS <i>Oil Condition</i> .....	78
Tabel 4.9 Hasil SOS <i>Percentage of Fuel</i> .....	79
Tabel 4.10 Hasil SOS <i>Total Base Number</i> .....	81
Tabel 4.11 Hasil SOS <i>Viscosity (V100)</i> .....	83
Tabel 4.12 Hasil Uji <i>Leak Test</i> .....	90