



## Table of Contents

Table of Contents .....	2
List of Abbreviations .....	2
List of Figures .....	3
List of Tables .....	5
List of Equation.....	6
Abstract .....	7
Zusammenfassung.....	8
1. Introduction.....	9
1.1. Background.....	9
1.2. Research Question .....	10
1.3. Research Objectives.....	11
1.4. Research Scope .....	11
1.5. Research Methodology .....	11
2. Conceptual Foundations of Production Process Optimization .....	12
2.1. Management of Production Process.....	12
2.2. Lean Six Sigma as Process Optimization Technique .....	13
2.1.1. Lean.....	13
2.1.2. Six Sigma .....	14
2.1.3. Lean Six Sigma .....	20
2.3. Business Process Management .....	21
2.4. Link Between Total Quality Management and Business Process Management.....	24
3. Data Collection and Analysis.....	25
3.1. Data collection .....	25
3.1.1. Company Profile .....	25
3.1.2. Company Hierarchy .....	26
3.1.3. Process Production.....	26

3.1.4. Company Current Situation .....	29
3.2. Data Analysis Method.....	30
3.2.1. Define Phase .....	30
3.2.2. Measure Phase .....	30
3.2.3. Analyze Phase.....	30
3.2.4. Improve Phase.....	31
3.2.5. Control Phase .....	31
3.3. Lean Six Sigma Analysis.....	31
3.1.1. Define Phases.....	31
3.1.2. Measure Phases .....	40
3.1.3. Analysis Phases.....	44
3.1.4. Improve Phases .....	55
3.1.5. Control Phases .....	66
3.4. Benefit Calculation .....	67
4. Conclusions.....	69
4.1. Summary .....	69
4.2. Recommendations for the company.....	70
4.3. Suggestions for future research.....	70
Bibliography.....	71
Appendix.....	75
Declaration .....	87



## List of Abbreviations

- Business Process Management (BPM)
- Business Process Management Notation (BPMN)
- Cause-Effect Diagram (CED)
- Cost of Poor Quality (COPQ)
- Critical To Business (CTB)
- Critical To Customer (CTC)
- Critical To Quality (CTQ)
- Decision Model and Notation (DMN)
- Defects Per Million Opportunities (DPMO)
- Defects Per Opportunities (DPO)
- Defects Per Unit (DPU)
- Define, Measure, Analysis, Improve, and Control (DMAIC)
- Define, Measure, Analyze, Design, and Verify (DMADV)
- Failure Modes and Effects Analysis (FMEA)
- Key Performance Indicator (KPI)
- Lean Six Sigma (LSS)
- Make-To-Order (MTO)
- Make-To-Stock (MTS)
- Plan–Do–Check–Act (PDCA)
- Plan, Do, Check, Act (PDCA)
- Quality Management (QM)
- Risk Priority Number (RPN)
- Seasonal Index (SI)
- Single-Minute Exchange Of Dies (SMED)
- Statistical Process Control (SPC)
- Supplier-Input-Process-Output-Customer (SIPOC)
- Total Productive Maintenance (TPM)
- Total Quality Management (TQM)
- Voice Of Customer (VOC)



## List of Figures

Figure 1: Cause-Effect Diagram .....	17
Figure 2: Pareto Diagram.....	18
Figure 3: Lean Six Sigma Models.....	20
Figure 4: Element of DMN .....	24
Figure 5: Company's Hierarchy .....	26
Figure 6: Operational Process Chart .....	27
Figure 7: Plastic Mat Sales 2019-2021 .....	29
Figure 8: The current business process model .....	32
Figure 9: The current manufacturing process model .....	34
Figure 10: Model fragments of choosing colors and dimension.....	35
Figure 11: Model fragments of acquiring materials.....	35
Figure 12: Model fragments of performing quality check .....	36
Figure 13: DRD model and corresponding decision table of evaluating plastic pellet.....	36
Figure 14: DRD model and corresponding decision table of evaluating aval .....	37
Figure 15: DRD model of cutting and weaving evaluation .....	37
Figure 16: DRD model and corresponding decision table of evaluating knot.....	37
Figure 17: DRD model and corresponding decision table of evaluating seam.....	38
Figure 18: Model fragments of shipping and invoice .....	38
Figure 19: Model fragments of terms payment.....	39
Figure 20: Data Production 2019-2022 (in meter).....	40
Figure 21: Data Product Defects 2019-2022 (in meter).....	41
Figure 22: p-Chart of defect.....	42
Figure 23: Pareto chart of type of problem .....	45
Figure 24: Types of major defects .....	45
Figure 26: Cause-Effect-Diagram for five missing lines in one mat .....	47
Figure 25: Cause-Effect-Diagram for three avals are missing in one line .....	47
Figure 27: Cause-Effect Diagram for the plastic mat is longer by 10 cm .....	50
Figure 28: TO-BE business process model .....	56
Figure 29: Process of confirming the order .....	57
Figure 30: DRD model and corresponding decision table of determination dimension type..	57
Figure 31: DRD model and corresponding decision table of determination plastic mat type .	58
Figure 32: Manufacturing process in TO-BE model .....	59



**The Application of Lean Six Sigma to Improve a Production Process: Case Study on PT. Wonorejo  
Makmur  
Abadi**

Ananda Noor Sholichah, Prof. Amin Wibowo, S.E., M.B.A., Ph.D.

Universitas Gadjah Mada, 2023 | Diunduh dari <http://etd.repository.ugm.ac.id/>

Figure 33: Move to aval process .....	60
Figure 34: Performing quality check in TO-BE model.....	61
Figure 35: DRD model and corresponding decision table of plastic mat evaluation (TO-BE) .....	61
Figure 36: DRD model and corresponding decision table of cutting evaluation (TO-BE) .....	61
Figure 37: DRD model and corresponding decision table of knotting evaluation (TO-BE)...	62
Figure 38: Monitor weaving process .....	62
Figure 39: Terms payment TO-BE model .....	63
Figure 40: Implementation plan.....	64
Figure 41: Forecast defect comparison .....	65



## List of Tables

Table 1: Tools Used .....	12
Table 2: Sigma Level and DPMO .....	16
Table 3: Data Type.....	17
Table 4: Basic Elements of BPMN .....	23
Table 5: Patented Brand.....	25
Table 6: CTQ in Weaving Process.....	40
Table 7: Defect Rate .....	41
Table 8: Calculation results of control chart p for defect .....	42
Table 9: DPU, DPO, DPMO and Sigma Level calculations.....	43
Table 10: Total defect each type .....	44
Table 11: FMEA three avals are missing in one line and five missing lines in one mat .....	52
Table 12: FMEA the plastic mat is longer by 10 .....	54
Table 13: Forecast total production and total defects .....	64
Table 14: Sigma value projection plan for proposed improvements .....	65
Table 15: Cost of raw material calculation .....	67
Table 16: Overhead cost calculation.....	67
Table 17: Operator cost calculation .....	68
Table 18: Cost of Poor Quality calculation.....	68
Table 19: COPQ value before and after implementation.....	68



**List of Equation**

Equation 1: Defect per Unit .....	15
Equation 2: Defects per Opportunities .....	16
Equation 3: DPMO.....	16
Equation 4: Sigma Level.....	16
Equation 5: Risk Priority Number .....	18
Equation 6: Cost of Poor Quality .....	19
Equation 7: Forecast Trend-Analysis.....	19
Equation 8: Seasonal Index.....	19
Equation 9: Defect Rate .....	41