

DAFTAR PUSTAKA

- Bain, E. C., 1939, Functions of the Alloying Elements in Steel, *American Society for Metals*, p. 36.
- Benhaddad, S., and Lee, G., 2001, Role of Microstructure in Sucker Rod String Failures in Oil Well Production, *Practical Failure Analysis*, Vol. 1, p. 47 – 54.
- Bloch, H. P. and Geitner, F. K., 1999, Practical Machinery Management for Process Plants : Vol. 2 : Machinery Failure Analysis and Troubleshooting, 3rd ed., Gulf Publishing Company, Houston.
- Budinski, K. G., 1989, Engineering Materials : Properties and Selection, 3rd ed., Prentice-Hall International Editions, New Jersey.
- Callister, W. D., 2001, Fundamentals of Materials Science and Engineering, 5th ed., John Wiley and Sons, New York.
- CIMCON Software, 2009, Oil and Gas Solutions : Sucker Rod Pump Automation, CIMCON Software (India) Pvt. Ltd, Ahmedabad.
- Colangelo, V. J. and Heiser, F. A., 1989, Analysis of Metallurgical Failure, 2nd ed., John Wiley and Sons, Singapore.
- Gupta, R. B., 2002, Material Science, Satya Prakashan, New Dehli.
- Honeycombe, R. W. K. and Bhadeshia, H. K. D. H., 1995, Steels: Microstructure and Properties, 2nd ed., Edward Arnold, London.
- Hutabarat, D., 2004, Analisis Kegagalan Pada Wheel Hub Pesawat FK 28 MK 3000, Program Studi Teknik Mesin Jurusan Teknik Mesin Fakultas Teknik Universitas Gadjah Mada, Yogyakarta.
- Hyne, N. J., 2007, Finding and Producing Oil and Gas : Chapter 8 : Completing The Well, *Lewis Mosburg's OIL & GAS NEWSLETTER*, Grand Rapids.
- Ilman, M. N., 2003, Rencana Program dan Kegiatan Pembelajaran Semester : Bahan Teknik, Universitas Gadjah Mada, Yogyakarta.
- Jones, D. R. H., Editor, 2001, Failure Analysis Case Studies II, 1st ed., Pergamon, Netherland.

- Kusmono, 2010, Report Failure Analysis of Sucker Rod at Medco Energy Co. Ltd, Oman, Departement of Mechanical and Industrial Engineering, Faculty of Engineering, Gadjah Mada University, Yogyakarta.
- Mobley, R. K., 1999, Root Cause Failure Analysis, Newnes, Boston.
- PT. Branky Bumiasri, 2009, Pumping Unit, *Drilling Production : Production Equipment*, PT. Branky Bumiasri, Jakarta.
- Sanusar, A., 1996, Analisis Kegagalan Tube Saturator Coil 101 B. P-II PT. Pusri Palembang, Program Pascasarjana Bidang Ilmu Teknik Universitas Indonesia, Jakarta.
- Smith, W. F., 1990, Principles of Material Science and Engineering, 2nd ed., McGraw-Hill Publishing Company, Singapore.
- Stevens, R. D., 2005, Sucker Rod Failure Analysis : A Special Report from Norris, Norris a Dover Company, Tulsa.
- Suryanarayana, A. V. K., 1979, Testing of Metallic Materials, Prentice-Hall of India, Private Limited, New Delhi.
- Tawancy, H. M., Ul-Hamid, A., and Abbas, N. M., 2004, Practical Engineering Failure Analysis, Marcel Dekker, New York.
- Tenaris Oilfield Service, 2005, API Sucker Rods, *Sucker Rods : General API and Premium Product*, Tenaris Oilfield Service, Houston.
- Trethewey, R. K., and Chamberlain, J., 1991, Corrosion : for Science and Engineering, 2nd ed, Longman Scientific and Technical, Singapore.