

DAFTAR ISI

HALAMAN JUDUL	i
NOMOR PERSOALAN	Error! Bookmark not defined.
HALAMAN PENGESAHAN	Error! Bookmark not defined.
SURAT PERNYATAAN BEBAS PLAGIASI	Error! Bookmark not defined.
MOTTO	Error! Bookmark not defined.
LEMBAR PERSEMBAHAN	Error! Bookmark not defined.
KATA PENGANTAR	Error! Bookmark not defined.
<i>ABSTRACT</i>	Error! Bookmark not defined.
INTISARI	Error! Bookmark not defined.
DAFTAR ISI	i
DAFTAR GAMBAR	iii
DAFTAR TABEL	iv
BAB I PENDAHULUAN	Error! Bookmark not defined.
1.1 Latar Belakang	Error! Bookmark not defined.
1.2 Rumusan Masalah	Error! Bookmark not defined.
1.3 Batasan Masalah	Error! Bookmark not defined.
1.4 Tujuan	Error! Bookmark not defined.
1.5 Metode Pengumpulan Data	Error! Bookmark not defined.
1.6 Sistematika Penulisan	Error! Bookmark not defined.
BAB II TINJAUAN PUSTAKA	Error! Bookmark not defined.
2.1 Konsep Desain <i>Implant</i>	Error! Bookmark not defined.

2.2	Perkembangan Implan Tulang Belakang	Error! Bookmark not defined.
2.3	Keausan Pada Tulang Belakang	Error! Bookmark not defined.
2.4	Faktor Keausan	Error! Bookmark not defined.
2.5	Kekasaran Permukaan	Error! Bookmark not defined.
2.6	Pengaruh Beban Terhadap Pengujian Keausan	Error! Bookmark not defined.
2.7	Pengaruh Pelumas Terhadap Pengujian Keausan	Error! Bookmark not defined.
2.8	Material Implan	Error! Bookmark not defined.
2.9	Titanium	Error! Bookmark not defined.
2.10	Ultra High Molecular Weight Polyethylene (UHMWPE)	Error! Bookmark not defined.
2.11	Pelumas (Bovine Serum)	Error! Bookmark not defined.
2.12	Tribology	Error! Bookmark not defined.
BAB III METODE PENELITIAN		Error! Bookmark not defined.
3.1	BAHAN PENELITIAN	Error! Bookmark not defined.
3.2	ALAT PENELITIAN	Error! Bookmark not defined.
3.3	PROSEDUR PENELITIAN	Error! Bookmark not defined.
3.4	SKEMA PENELITIAN	Error! Bookmark not defined.
3.5	HAMBATAN PENELITIAN	Error! Bookmark not defined.
BAB IV HASIL PENELITIAN		Error! Bookmark not defined.
4.1	Uji Komposisi Bahan	Error! Bookmark not defined.
4.2	Hasil Pengukuran Berat	Error! Bookmark not defined.
4.2.1	Laju Keausan Titanium	Error! Bookmark not defined.
4.2.2	Laju Keausan UHMWPE	Error! Bookmark not defined.

4.3 Hasil Pengujian Kekasaran Permukaan UHMWPE dan Titanium **Error! Bookmark not defined.**

BAB V PENUTUP **Error! Bookmark not defined.**

5.1 Kesimpulan **Error! Bookmark not defined.**

5.2 Saran **Error! Bookmark not defined.**

DAFTAR GAMBAR

Gambar 1. 1 Susunan tulang belakang manusia (Mow dan Hayes, 1997)..... **Error! Bookmark not defined.**

Gambar 1. 2 Susunan dua ruas tulang belakang lumbar (Mow dan Hayes, 1997)
..... **Error! Bookmark not defined.**

Gambar 3. 1 Pasangan ball UHMWPE dan Socket titanium**Error! Bookmark not defined.**

Gambar 3. 2 Logam Titanium hasil cor **Error! Bookmark not defined.**

Gambar 3. 3 Batu langsol..... **Error! Bookmark not defined.**

Gambar 3. 4 Mesin Bubut **Error! Bookmark not defined.**

Gambar 3. 5 Mesin *Pollishing*..... **Error! Bookmark not defined.**

Gambar 3. 6 Mesin *Electronic Balance* **Error! Bookmark not defined.**

Gambar 3. 7 *Ultrasonic Cleanser* **Error! Bookmark not defined.**

Gambar 3. 8 Alat *Surface Roughness* **Error! Bookmark not defined.**

Gambar 3. 9 *Centrifuge*..... **Error! Bookmark not defined.**

Gambar 3. 10 Pembuatan pelumas *bovine blood serume***Error! Bookmark not defined.**

Gambar 3. 11 Alat pengujian kekasaran permukaan**Error! Bookmark not defined.**

Gambar 3. 12 *Spine Simulator*..... **Error! Bookmark not defined.**

Gambar 3. 13 Skema Penelitian **Error! Bookmark not defined.**

Gambar 4. 1 Grafik Komposisi Bahan.....	Error! Bookmark not defined.
Gambar 4. 2 Laju Keausan Titanium.....	Error! Bookmark not defined.
Gambar 4. 3 Laju Keausan UHMWPE	Error! Bookmark not defined.
Gambar 4. 4 Grafik Kekasaran Permukaan Pada Spesimen Titanium	Error! Bookmark not defined.
Gambar 4. 5 Grafik Kekasaran Permukaan pada Spesimen UHMWPE.....	Error! Bookmark not defined.
Gambar 4. 6 Perbandingan Grafik Kekasaran Permukaan Titanium dan UHMWPE.	Error! Bookmark not defined.

DAFTAR TABEL

Tabel 4. 1 <i>Quantitative Results for: Titanium</i>	Error! Bookmark not defined.
Tabel 4. 2 Perhitungan berat awal dan berat rata-rata setiap siklus pengujian.	Error! Bookmark not defined.
Tabel 4. 3 Perhitungan hasil pengurangan berat spesimen pada setiap siklus uji, dan berhenti setiap mencapai $2,5 \times 10^5$ siklus.	Error! Bookmark not defined.
Tabel 4. 4 Perhitungan hasil pengurangan berat spesimen UHMWPE pada setiap siklus uji, dan berhenti setiap mencapai $2,5 \times 10^5$ siklus.	Error! Bookmark not defined.
Tabel 4. 5 Pengurangan Volume UHMWPE	Error! Bookmark not defined.
Tabel 4. 6 Kekasaran Awal Spesimen Titanium dan UHMWPE sebelum diuji Keausan.....	Error! Bookmark not defined.
Tabel 4. 7 Kekasaran Spesimen Titanium dan UHMWPE setelah diuji Keausan pada siklus ke 250000.	Error! Bookmark not defined.
Tabel 4. 8 Kekasaran Spesimen Titanium dan UHMWPE setelah diuji Keausan pada siklus ke 500.000	Error! Bookmark not defined.

Tabel 4. 9 Kekasaran Spesimen Titanium dan UHMWPE setelah diuji Keausan pada siklus ke 750.000 **Error! Bookmark not defined.**