



DAFTAR PUSTAKA

- Al-Qaisia, A. A. dan Meneghetti, U., 1997, Crack Detection in Plates by Sensitivity Analysis, Article in Proceedings of SPIE - The International Society for Optical Engineering, pp. 1831-1830
- Aminuddin, J., 2008, Dasar-Dasar Fisika Komputasi Menggunakan Matlab, Gava Media, Yogyakarta
- ASTM E565., 3002, Standard Practical for Static Load Test for Shear Resistance of Framed Walls for Building, Designation Vol 405, ASTM International, United States.
- Astuti, K. P., 2018, Studi Numerik dan Eksperimental Distribusi Tegangan dan Regangan Beton, Skripsi Teknik Sipil, Malang.
- Bandara, R.P., Tommy, H. T. C., dan Thambiratnam, D. P., 2014, Structural damage detection method using frequency response functions, Structural Health Monitoring Vol. 13(4), pp. 418-429.
- Betti, M. dan Galano, L., 2012, Seismic Analysis of Historic Masonry Buildings: The Vicarious Palace in Pescia (Italy), Article., Department of Civil and Environmental Engineering (DICEA), University of Florence, Via di Santa Marta, Florence, Italy.
- Bintang, M dan Maulana, R., 2010, Pengaruh Dinding Bata Merah dalam Menahan Beban Lateral, Skripsi, Politeknik Negeri Bandung.
- Boen, T., 2016, Belajar dari Kerusakan Akibat Gempa Bumi Bangunan Tembokan Nir-Rekayasa di Indonesia, Gadjah Mada University Press, Yogyakarta.
- Brincker, R., Andersen, P. dan Kirkegarrd, P.H., 1995, Damage Detection in Laboratory Concrete Beams, Fracture & Dynamics, Paper no. 61.
- Brodsky, A., Rabinovitch, O. dan Yankelevsky, D.Z., 2018, The Interaction of an Infill Wall with a Surrounding Frame During an Earthquake, in: Thessaloniki. Presented at the 16th European Conference on Earthquake Engineering, p. 12.
- BSN, 2019, Tata Cara Perencanaan Ketahanan Gempa untuk Struktur Bangunan Gedung dan non-gedung.
- BSN, 2000. Bata Merah Pejal untuk Pasangan Dinding, SNI 15-2094-2000.
- Budiwati, I.A.M., Sutapa, A.A.G., Kurniawan, I.K.E., 2019, Studi Eksperimental Perilaku Tekan Pasangan Bata dan Bahan Pembentuknya. Jurnal Ilmiah Teknik Sipil-A Scientific Journal of Civil Engineering 23, 88–95.
- Caetano, E., 1992, Identificação Experimental de Parâmetros Dinâmicos em Sistemas Estruturais, Master Thesis”, Engineering Faculty of University of Porto, Portugal.
- Ceroni, F., Sica, S., Pecce, M. R. dan Garafano., A., 2014, Evaluation of the Natural Vibration Frequencies of a Historical Masonry Building Accounting for SSI, Soil Dynamics and Earthquake Engineering, pp. 95-101.
- Chance, J., Tomlinson, G. R., dan Worden, K., 1994, A Simplified Approach to The Numerical and Experimental Modeling of The Dynamics of a Cracked Beam, in Proc. of the 12th International Modal Analysis Conference, pp. 778–785.
- Chen, B., dan Nagarajaiah, S., 2013, Flexibility-based Structural Damage Identification Using Gauss–Newton Method, Sadhana Vol. 38, Part 4.
- Chen, Y., dan Swamidas, A. S. J., 1994, Dynamic Characteristics and Modal Parameters of a Plate with A Small Growing Surface Crack, in Proc. of the 12th International Modal Analysis Conference, pp. 1155–1161.



- Choi, S., Park, S., dan Stubbs, N., 2005, Nondestructive damage detection in structures using changes in compliance, International Journal of Solids and Structures, pp. 4494-4513.
- Chopra, A.K., 2001, Dynamics of Structures, Theory and Applications to Earthquake Engineering, Second Edition, Prentice Hall.
- Christou, P., Venizelou, C., 2019, The Contribution of the Infill Walls to the Lateral Strength of Concrete Frames. TOBCTJ 13, 114–122. <https://doi.org/10.2174/1874836801913010114>
- Clough, R.W. dan Penzien, J., 1993, Dynamics of Structures, Second Edition, McGraw-Hill international Editions.
- Dardiri, A., 2012, Analisis Pola, Jenis dan Penyebab Kerusakan Bangunan Gedung Sekolah Dasar, Jurnal Teknologi dan Kejuruan Vol 35 No.1, Februari 2012 p.21-80.
- Dewesoft v7.0., 2009, Data acquisition, processing, analyzing and storage software, Dewesoft Tutorials.
- De Angelis, A. dan Pecce, M.R., 2020, The Role of Infill Walls in the Dynamic Behavior and Seismic Upgrade of a Reinforced Concrete Framed Building, Front. Built Environ. 6, 590114. <https://doi.org/10.3389/fbuil.2020.590114>.
- Dirjen Cipta Karya, Departemen PU., 2006, Pedoman Teknis Rumah dan Bangunan Gedung Tahan Gempa.
- Dirjen Cipta Karya, Departemen PU., 2008, Peraturan Menteri Pekerjaan Umum No. 24/PRT/M/2008 tanggal 30 Desember 2008 tentang Pedoman Pemeliharaan dan Perawatan Bangunan Gedung.
- Doebling, S. W., Farrar, C. R., dan Prime, M. B., 1998, A Summary Review of Vibration-Based Damage Identification Methods, Los Alamos National Laboratory.
- Dong C., Zhang, P. Q., Feng, W. Q., dan Huang, T. C., 1994, The Sensitivity Study of The Modal Parameters of a Cracked Beam, in Proc. of the 12th International Modal Analysis Conference, pp. 98–104.
- Eclund, A., 2006, Measurement and Evaluationof Cable Forces in the Alvsborg Brigde, Master Thesis, Structural Design and Bridges Royal Institute of Techology, Stockholm.
- Elmenshawi, A., Sorour, M., Mufti, A., Jaeger, L.G., Shrive, N., 2010, Damping mechanisms and damping ratios in vibrating unreinforced stone masonry, Engineering Structures 32, 3269–3278. <https://doi.org/10.1016/j.engstruct.2010.06.01>
- Elnashai, A., Sarno, L.D., 2008. Fundamentals of Earthquake Engineering, 1st ed. John Wiley & Sons, Inc.
- Erlina, R., 2015, Vibration Serviceability of Grha Sabha Pramana Auditorium Under Human-Induced Excitation, Thesis, Department of Civil and Environmental Engineering, UGM, Yogyakarta.
- Ewins, D.J., 2000, Modal Testing, Theory, Practice and Aplication, Second Edition, Research Studies Press LTD, Baldock, Hertfordshire, England.
- Fadillawati, S., 2000, Deteksi Kerusakan Balok Beton Non Prismatis Dengan Perubahan Ragam Kelengkungan, Thesis, DTSL, UGM.
- Faizah, R., 2021, Perilaku Dinamik Dinding Pasangan Batu In-Plane Menggunakan Spesi Mortar Serutan Karet Ban Bekas, Disertasi, DTSL, UGM.
- Farrar, C. R., Doebling, S. W. dan Nix, D. A., 2001, Vibration-Based Structural Damage Identification, Mathematical, Physical and Engineering Sciences, Vol.359, No. 1778, pp. 131-149.



- FEMA 273, 1997, NEHRP Guidelines for The Seismic Rehabilitation of Buildings, The Federal Emergency Management Agency, Washington DC.
- FEMA 356, 2000, Prestandard and Commentary for The Seismic Rehabilitation of Buildings, The Federal Emergency Management Agency, Washington DC.
- Garaygordobil, J. C. A., 2005, Dynamic identification and model updating of historical buildings, State-of-the-art review, Structural Analysis of Historical Constructions, pp. 499-504.
- Guidobaldi, M., Gentile, C. dan Saisi, A., 2015, One-year dynamic monitoring of a masonry tower, MATEC Web of Conferences.
- Hamid. A., 2011, "Praktikal Vibrasi Mekanik, Teori dan Praktik", Graha Ilmu, Yogyakarta.
- Hasrizam, C. M dan Fawazi, N., 2017, Damage Identification Based on Curvature Ragam Bentuk using Cubic Polynomial Regression and Chebyshev Filters, Materials Science and Engineering, pp. 1-7.
- Humes, B., 2006, Basic Vibration Analysis, Retrieved on June 12-2013 (865).
- Juang, J-N., 1994, Applied System Identification. Prentice Hall Englewood Cliffs, New Jersey, USA.
- J. Snow and C. Torney, "Short guide: Lime mortars in traditional buildings," *Short Guid.*, vol. 6, pp. 16–18, 2014.
- Karyasa, T. B., 2010, Dasar-dasar Getaran Mekanis, Andi, Yogyakarta.
- Kevizky, L., Bars, R., Hetthessy, J. dan Banyasz, C., 2019, Control Engineering: Matlab Exercises, Advanced Textbooks in Control and Signal Processing, Springer Nature Singapore.
- Kondo, I. and Hamamoto, T., 1994, Local Damage Detection of Flexible Offshore Platforms Using Ambient Vibration Measurements, in Proc. of the 4th International Offshore and Polar Engineering Conf., Vol. 4, pp. 400–407.
- Lin, K., Totoev, Y., Liu, H., Guo, T., 2016. In-Plane Behaviour of a Reinforcement Concrete Frame with a Dry Stack Masonry Panel. Materials 9, 108. <https://doi.org/10.3390/ma9020108>.
- Lindeburg, M. R., McMullin, K.M., 2008, Seismic Design of Building Structures: A Professional's Introduction to Earthquake Forces and Design Details, Ninth. ed. Professional Publication, Inc., Belmont, California.
- Maia, N.M.; dan Silva, J.M., 1997, Theoretical and Experimental Modal Analysis, Research Studies Press LTD, England.
- Masciotta, M. G., Ramos, L. F., Vasta, M. dan Laurencio, P. B., 2017, Damage Identification and Seismic Vulnerability Assessment of a Historic Masonry Chimney, Annals of Geophysics, S0442.
- Meli, R., Brzev, S., Astroza, M., Boen, T., Crisafulli, F., Dai, J., Farsi, M., Hart, T., Mebarki, A., Moghadam, A.s., Quiun, D., Tomazevic, M. dan Yamin, L., 2011, Seismic Design Guide for Low – Rise Confined Masonry Buildings, Earthquake Engineering Research Institute, California.
- Montalvao, D., Ribeiro, A. M. R. dan Silva, D. J., 2010, A Numerical-Experimental Method for the Damage Location in Composite Plates, Proceedings of the Tenth International Conference on Computational Structures Technology, paper 52.
- Muslikh, H., Iman, M. dan Setiawan, A. F., 2021, "Pemodelan Elemen Hingga Struktur Menggunakan Abaqus", Beta Offset, Yogyakarta.
- Novak, M., 1974, "Dynamic Stiffness and Damping of Pile. Can", Geotech Journal 11, 574– 598. <https://doi.org/10.1139/t74-059>.



- Nwosu, D. I., Swamidas, A. S. J., Guigne, J. Y., dan Olowokere, D. O., 1995, Studies on Influence of Cracks on The Dynamic Response of Tubular T-Joints for Nondestructive Evaluation, in Proc. of the 13th International Modal Analysis Conference, pp. 1122–1128.
- Pandey, A.K.; Biswas, M.; dan Samman, M.M, 1991, Damage Detection from Changes in Curvature Shape Modes”, Journal of Sound and Vibration, Vol. 145, No. 2, pp. 321-332.
- Pawirodikromo, W., 2017,”, Cetakan Pertama, Penerbit Pustaka Pelajar, Yogyakarta.
- Paulay, T., Priestley, M.J.N., 1992, Seismic Design of Reinforced Concrete and Masonry Buildings. John Wiley & Sons, Inc.
- Paz, M., 1996, Dinamika Struktur Teori dan Perhitungan, Edisi Kedua, Penerbit Erlangga, Jakarta.
- Peeters, B, 2000, System Identification and Damage Detection in Civil Engineering, PhD Thesis, Catholic University of Leuven, Belgium.
- Prayuda, H., 2015, Prediksi Gaya Lateral In Plane Melalui Perubahan Frekuensi Alami dan Redaman Struktur Dinding Pasangan Bata ½ Batu Dengan Spesi 1 Pc : 4 Kp : 10 Ps Melalui Analisis Getaran Mikro, Departemen Teknik Sipil dan Lingkungan, UGM.
- Priyosulistyo, H.2010, Struktur Beton Bertulang I, Biro Penerbit, Teknik Sipil dan Lingkungan, Universitas Gadjah Mada, Yogyakarta.
- Priyosulistyo, H., 2022, Analisis Dinamik Struktur dan Aplikasinya di Bidang Teknik Sipil, Gadjah Mada University Press, Yogyakarta.
- Ramos, L. F., Roeck, G. D., Laurencio, P. B. dan Costa, A. C., 2006, Damage Identification Based on Vibration Measurements Applied to Masonry Structures, Proceedings of ISMA, pp. 925-940.
- Ramos, L. F., Mevel, L., Laurencio, P. B. dan Roeck, G. D., 2007, Dynamic Monitoring of Historical Masonry Structures for Damage Identification, University of Minho, Portugal.
- Remirez, R., 1985, The Fundamentals and Concepts, Prentice-Hall Inc, New Jersey, USA.
- Rihard, F., Arfiadi, Y., dan Parung, H., 2016, Comparative Study of Mode Shape Curvature and Damage Locating Vector Methods for Damage Detection of Structures, SCESCM, Procedia Engineering hal. 1263-1271.
- Rodrigues, J., 2004, Identificação Modal Estocástica, Métodos de Análise e Aplicações em Estruturas de Engenharia Civil, PhD Thesis, Engineering Faculty of University of Porto, Portugal.
- Rucevskis, S. dan Wesolowski, M., 2010, Identification of Damage in A Beam Structure by Using Ragam Bentuk Curvature Squares, Shock and Vibration 17, PP. 601-610.
- Rucevskis, S. dan Chate, A., 2013, Damage Identification in a Plate-Like Structure using Modal Data, AVIATION Volume 13(2), pp. 45-51.
- Rucevskis, S., Akishing, P. dan Chate, A., 2015, Numerical and Experimental Study on the Application of mode shape Curvature for Damage Detection in Plate-Like Structures, Solid State Phenomena Vols 220-221, pp 264-270.
- Rucevskis, S., Janeliuthis. R. dan Akishing, P., 2016, Mode shape-based damage detection in plate structure without baseline data, Structural Control and Health Monitoring, hal. 1180-1893.



- Saraj dan Fateme, M., 2008, A Comprehensive Approach Towards the Classification of Cracks in Un-Reinforced Masonry Building, IUST International Journal of Engineering Science Vol. 19 No. 6, pp. 41-45.
- Satyarno, I., Nawagalam, P. dan Pratomo, R.I., 2012, Belajar SAP 2000 Seri 1 dan 2, Edisi kedua, Zamil Publishing, Yogyakarta.
- Scherer, G. W., 2006, Internal Stress and Cracking in Stone and Masonry, PRISM Engineering Quad E-319, Princeton University, USA.
- Segura, J., Pelà, L., Roca, P., 2018. Monotonic and cyclic testing of clay brick and lime mortar masonry in compression. Construction and Building Materials 193, 453–466. <https://doi.org/10.1016/j.conbuildmat.2018.10.198>
- Sönmez, E. dan Dönmez, C., 2014, Effect of Infill Wall Stiffness Variations on the Behavior of Reinforced Concrete Frames under Earthquake Demands, Presented at the Second European Conference on Earthquake Engineering and Seismology, Istanbul, p. 12.
- Stubbs, N. dan Osegueda, R., 1990, Global Non-Destructive Damage Evaluation in Solids, Modal Analysis: The International Journal of Analytical and Experimental Modal Analysis, Vol. 5, No. 2, pp. 67–79.
- Stubbs, N., Kim, J. T. dan Topole, K., 1992, An Efficient and Robust Algorithm for Damage Localization in Offshore Platforms, in *Proc. ASCE Tenth Structures Congress*, pp. 543–546.
- Stubbs, N. dan Kim, J. T., 1996, Damage Localization in Structures Without Baseline Modal Parameters, AIAA Journal Vol. 34, No. 8, pp. 1644-1649.
- Tanjung, J. dan Maidiawati, M., 2016, Studi Eksperimental tentang Pengaruh Dinding Bata Merah Terhadap Ketahanan Lateral Struktur Beton Bertulang, Journal of Civil Engineering 23, 99-106–106, <https://doi.org/10.5614/jts.2016.23.2.2>.
- Tanudjaja. H., 2007, Pengolahan Sinyal Digital dan Sistem Pemrosesan Sinyal, Andi, Yogyakarta.
- Topole, K. G. dan Stubbs, N., 1995a, Nondestructive Damage Evaluation of a Structure from Limited Modal Parameters, *Earthquake Engineering and Structural Dynamics*, Vol. 24, No. 11, pp. 1427-1436.
- Topole, K. G. dan Stubbs, N., 1995b, Nondestructive Damage Evaluation in Complex Structures from a Minimum of Modal Parameters, *Modal Analysis – The International Journal of Analytical and Experimental Modal Analysis*, Vol. 10, No. 2, pp. 95-103.
- Torney, C., 2014, Lime Mortars in Traditional Buildings: Short Guide 6”, Historic Scotland Alba Aosmhor, Scotland.
- Totoev, Zarevich, Y., Kun, L., 2012, Frictional Energy Dissipation and Damping Capacity of Framed Semi-Intrlocking Masonry Infill Panel, in: 15th International Brick and Block Masonry Concrete, Presented at the 15th International Brick and Block Masonry Concrete, Florianapolis Brazil, p. 10.
- Vera, C. O dan Chouw, N., 2017a, Damage Identification of Unreinforced Masonry Panels Using Vibration-Based Techniques, Shock and Vibration Vol. 2017, pp. 1-14.
- Vera, C. O., Ingham, J. dan Chouw, N., 2017b, Vibration-Based Damage Identification of An Unreinforced Masonry House Model, Advances in Structural Engineering, Vol. 20(3), pp. 331–351.
- Velez, L.A., 2014. Seismic behavior of concrete block masonry buildings (Thesis). Universidade do Minho, Escola de Engenharia.
- Vierck, R. K., 1995, Analisis Getaran, Refika Aditama, Bandung.



UNIVERSITAS
GADJAH MADA

**DETEKSI RETAK DINDING PASANGAN BATU BATA DENGAN MORTAR CAMPURAN KAPUR, BUBUK
BATA MERAH DAN PASIR
MENGGUNAKAN ANALISIS GETARAN**

FIRNIMUS K. BHARA, Prof. Ir. Henricus Priyosulistyo, M.Sc., Ph.D.; Ir. Suprapto Siswosukarto, Ph.D; Dr.-Ing. Ir. Djoko

Universitas Gadjah Mada, 2023 | Diunduh dari <http://etd.repository.ugm.ac.id/>

- Widodo, 2001, Respons Dinamik Struktur Elastik, 1st ed. UII Press, Yogyakarta.
- Wisnumurti, Dewi, S. M. dan Soehardjono, A., 2013, Investigation of Elasticity, Compression and Shear Strength of Masonry Wall from Indonesian Clay Brick, International Journal of Engineering Research and Applications (IJERA), pp. 259-263.
- Wu, F., Wang, H.-T., Li, G., Jia, J.-Q., 2017, Seismic Performance of Traditional Adobe Masonry Wall Subjected to In-Plane Cyclic Loading, Materials and Structures 50. <https://doi.org/DOI: 10.1617/s11527-016-0927-0>
- Yao, G. C. C. dan Chang, K. C., 1995, A Study of Damage Diagnosis from Earthquake Records of a Steel Gable Frame, Journal of the Chinese Institute of Engineers, Vol. 18, No. 1, pp. 115-123.