

DAFTAR PUSTAKA

- Ansys.com. (n.d.). Company Information. Retrieved from Ansys.com: <https://www.ansys.com/company-information>
- Bonar, Immanuel, M., Saptono, Hendro, & Islamiyati. (2022, December 15). *PERLINDUNGAN HUKUM TERHADAP PENGGUNA JASA TRANSPORTASI KERETA API ARGO MURIA_002 DG 2021*. Retrieved from Universitas Diponegoro Institutional Repository: <https://eprints2.undip.ac.id/id/eprint/5359/>
- Cheng, L. Z., Liu, D. K., Wang, Y., & Chen, A. Q. (2019). Load distribution and contact of axle box *Bearings* in electric multiple units. *International Journal of Simulation Modelling*, 18(2), 290–301. [https://doi.org/10.2507/IJSIMM18\(2\)475](https://doi.org/10.2507/IJSIMM18(2)475)
- Chong, S. Y., & Shin, H. (2010). A review of health and operation monitoring technologies for trains. *SMART STRUCTURES AND SYSTEMS*, 6, 1079–1105. <https://doi.org/10.12989/sss.2010.6.9.1079>
- Darmo, S., Bahiuddin, I., Handoko, P., Rizki Priatomo, H., Kuncoro, M., Priyambodo, S., Haryanto, Fatah Rahman, N., Machmuddi Kanosri, A., & Winarno, A. (2022). Failure analysis of double-row tapered roller bearing outer ring used in Coal Wagon Wheelset. *Engineering Failure Analysis*, 135. <https://doi.org/10.1016/j.engfailanal.2022.106153>
- INKA. (2015, March 10). *Mengenal Istilah Bogie Pada Kereta Api (Bag.1)*. Retrieved April 6, 2023, from INKA: <https://www.inka.co.id/berita/58>
- KNKT. (2019). *Laporan Investigasi Kecelakaan Perkeretaapian*. KNKT RI, Anjlok KA 3003D. KNKT.18.09.09.02. Retrieved April 04, 2023
- Martinov, I. E., Truvanofa, A. V., & Pethukov, V. M. (2018). Study of the Effect of *Adapter* Design on the Load Distribution in the *Bearing* Units of Freight Cars. *International Journal of Engineering & Technology*, 7(4), 147-151. doi:10.14419/ijet.v7i4.3.19725
- Nam, J. (2014). *How Railway Systems Work*. AuthorHouse.
- Nurato, N., & Kushardiyanto, K. (2016). Analisis Kekuatan Gandar pada Kereta Api Penumpang. *SINERGI*, 20(2), 101–108. <https://doi.org/10.22441/sinergi.2016.2.003>
- PT. KAI. (2019). *Data Timbangan Berat Muatan*. Direktorat Keselamatan dan Keamanan PT. KAI (Persero).
- Standar dan Tatacara Perawatan Prasarana Perkeretaapian, Menteri Perhubungan RI (2011).
- Tarawneh, C., Sotelo, L., Villarreal, A., De Los Santos, N., Lechtenberg, R., & Jones, R. (2016). *Temperature Profiles of Railroad Tapered Roller*

Bearings With Defective Inner and Outer Rings.

<https://doi.org/10.1115/JRC2016-5816>

Tarawneh, C., Montalvo, J., & Wilson, B. (2021). Defect detection in freight railcar tapered-roller Bearings using vibration techniques. *Railway Engineering*
Tedrail. (2020). *Product Bogie*. Retrieved from tedrail.com:
<http://www.tedrail.com/Products/classify/Wearing%20Parts>