

## DAFTAR PUSTAKA

- @rp4rts. (2021, 1 19). *Cara Kerja System Hydraulic Pada Alat Berat*. Retrieved from Arparts: <https://arparts.id/cara-kerja-system-hydraulic-pada-alat-berat/>
- ASTM D 2000-99. (1999). *Standard Classification System for Rubber Products in Automotive Applications*. West Conshohocken, USA: American Society of Testing & Materials.
- ASTM D2240-15. (2017). *Standard Test Method for Rubber Property-Durometer Hardness*. West Conshohocken, USA: American Society of Testing & Materials.
- ASTM D471-16. (2016). *Standard Test Method for Rubber Property-Effect of Liquids*. USA: American Society of Testing & Materials.
- Bagaskara, F. S., Aditya, M. R., Aldyansyah, D., Aji, D. M., Sitanggang, A. F., Khairi, M. M., & Paundra, F. (2023). Perawatan Mesin Alat Berat Wheel Loader PT. XYZ. *Jurnal Teknik Mesin, Vol. 20 No. 1*, 18-23.
- Ding, S., A, G. L., Ma, J., & Gao, M. (2023). Failure Analysis Of A Loader Hydraulic Cylinder and Its End Cap Structure Improvement. *Engineering Failure Analysis*, 1-14.
- Flitney, R. (2007). *Seals and Sealing Handbook* (Vol. Vol 5). Burlington, British: Elsevier Ltd.
- Hydro, M. (2020, 6 12). *Pengertian Hydraulic System, Keuntungan dan Cara Perawatan*. Retrieved from Hydropower: <https://www.ciptahydropower.com/hydraulic-system/#:~:text=Hydraulic%20system%20atau%20sistem%20hidrolik,produktivitas%20semakin%20efisien%20dan%20efektif>

- Iskandar, Ismy, A. S., Sariyusda, Darmein, & Zaini. (2021). Analisa Kerusakan Hidrolik Boom Cylinder Excavator Komatsu PC200-8 Dengan Menggunakan Metode FMEA. *Jurnal Mesin Sains Terapan* , Vol 5 No. 1, 8-11.
- ISO 1629. (2013). *Rubber and Latics - Nomenclature*. Switzerland: International Standard Organization.
- ISO 1817. (2011). *Rubber, Vulcanized or Thermoplastic - Determination of The Effect of Liquid* (Vol. Vol 5). Switzerland: International Standard Organization.
- ISO 23529-2010. (2010). *Rubber - General Procedures for Preparing and Conditioning Test Pieces for Physical Test Methods*. Switzerland: International Standard Organization.
- ISO 3448. (1992). *Industrial Liquid Lubricant-Viscosity Classification* (Vol. Vol 2). Switzerland: International Standard Organization.
- ISO 48-2. (2018). *Rubber, Vulcanized, or Thermoplastic - Determination of Hardness - Part 2 "Hardness Between 10 IRHD and 100 IRHD"* (Vol. Vol. 1). Switzerland: International Standard Organization.
- Kurniawan , C. (2017). *Analisis Kerusakan O-Ring Seal Pada Hydraulic Cylinder Telescopic Boom Reach Stacker Kalmar DRF 450-60 S5M*. Yogyakarta: Universitas Gadjah Mada.
- Mofidi, M. (2009). *Tribology of Elastomeric Seal Materials*. Lulea: University of Technology.
- NOK Corporation. (2001). *Packing Hydraulic Sealing System*. Tokyo: NOK Group.
- NOK Corporation. (2003). *Oil Seals*. Tokyo, Japan: NOK Group.
- Nugraha, A. C. (2022). *Analisa Kerusakan Hydraulic Cylinder Boom Pada Excavator PC200-8*. Surakarta: Universitas Muhammadiyah Surakarta.
- Penambang. (2014, 11 5). *Directional Control Valve*. Retrieved from Penambang: <https://penambang.com/directional-control-valve>

- Qiu, Z., Min, R., Wang, D., & Fan, S. (2022). Energy Features Fusion Based Hydraulic Cylinder Seal Wear and Internal Leakage Fault Diagnosis Method. *Measurement*, 1-13.
- Rizki S.T., M. (n.d.). *14 Komponen Wheel Loader dan Fungsinya*. Retrieved from Yale Tools: <https://yaletools.com/id/komponen-wheel-loader/>
- Saifany, F. (2022). *Analisis Kerusakan Dust Seal Pada Silinder Hidrolik Hoist Rigid Dump Truck Komatsu HD 465-5*. Yogyakarta: Universitas Gadjah Mada.
- Samidi. (2020, 4 23). *Apakah Itu Dust Seal Dan Fungsi Dust Seal Pada Cylinder*. Retrieved from Samiinstansi: <http://www.samiinstansi.com/2020/04/apakah-itu-dust-seal-dan-fungsi-dustsealpadacylinder.html>
- Siswandi. (2022). *Analisa Kerusakan Sistem Hidraulik Pada Boom Silinder Excava 200 Pindad*. Surakarta: Universitas Muhammadiyah Surakarta.
- Syarifuddien, F. (2019). *Analisa Kerusakan Cylinder Hydraulic Bucket Excavator XGMA XG822EL*. Surakarta: Universitas Muhammadiyah Surakarta.
- Tawancy, H. M., Ul-Hamid, A., & Abbas, N. (2004). *Practical Engineering Failure Analysis*. New York, USA: Marcel Dekker, Inc.
- Trellerborg. (2007). *Hydraulic Seals-linear*. Skane, Swedia: Trellerborg AB.
- Utomo, K. Y. (2022). Analisis Ketahanan Seal Pada Batang Hidrolik Excavator Tipe EC200D. *Jurnal Kewarganegaraan*, 6813-6832.
- Yuken Kogyo. (2006). *Basic Hydraulic and Components*. Tokyo, Japan: Yuken Kogyo Co., Ltd.
- Yuniari, A., & Sarengat, N. (2013). Sifat Fisika dan Analisis Gugus Fungsi Karet Seal O-Ring Dari Bahan Termoplastik Elastomer Nitrile Butadine Rubber (NBR) dan Polyvinyl Chlorodine. *Majalah Kulit, Karet, dan Plastik*, Vol. 29 No. 1, 21-30.