

DAFTAR PUSTAKA

- Ahlinhan, M.F., Koube, M.B., dan Adjovi, C.E., 2016. Assessment of the Internal Instability for Granular Soils Subjected to Seepage. *Journal of Geoscience and Environment Protection*, 04 (06), 46–55.
- Ali, H. dan Choi, J., 2019. A Review of Underground Pipeline Leakage and Sinkhole Monitoring Methods Based on Wireless Sensor Networking. *Sustainability*, 11 (15), 4007.
- American Association of State Highway and Transportation Officials (AASHTO), 2007. *Highway Drainage Guidelines*. 4 ed. Washington, D.C.: AASHTO.
- Ana, E., Bauwens, W., Pessemier, M., Thoeye, C., Smolders, S., Boonen, I., dan De Gueldre, G., 2009. An investigation of the factors influencing sewer structural deterioration. *Urban Water Journal*, 6 (4), 303–312.
- Benahmed, N. dan Bonelli, S., 2012. Internal erosion of cohesive soils: laboratory parametric study. *International Conference on Scour and Erosion*, 6, 1041–1048.
- Bonelli, S., 2013. *Erosion in Geomechanics Applied to Dams and Levees*. 1 ed. John Wiley & Sons, Inc.
- Chao, H., Tan, Y., dan Su, Z.-K., 2025. Ground failure and soil erosion caused by bursting of buried water pipeline: experimental and numerical investigations. *Engineering Failure Analysis*, 167, 108965.
- Dastpak, P., Sousa, R.L., dan Dias, D., 2023. Soil Erosion Due to Defective Pipes: A Hidden Hazard Beneath Our Feet. *Sustainability*, 15 (11), 8931.
- Federal Highway Administration, F., 2012. *Hydraulic Design Of Highway Culverts*. Washington, DC, USA: Federal Highway Administration (FHWA), No. FHWA-HIF-12-026.
- Guo, S., Shao, Y., Zhang, T., Zhu, David.Z., dan Zhang, Y., 2013. Physical Modeling on Sand Erosion around Defective Sewer Pipes under the Influence of Groundwater. *Journal of Hydraulic Engineering*, 139 (12), 1247–1257.
- Hardiyatmo, H.C., 2012. *Tanah Longsor dan Erosi : Kejadian dan Penanganan*. Yogyakarta: UGM Press.
- Hardiyatmo, H.C., 2023. *Pemeliharaan Jalan Raya: Perkerasan, Drainase, Longsor*. Yogyakarta: UGM Press.
- Hasmar, H.A.H., 2012. *Drainasi Terapan*. 1 ed. Yogyakarta: UII Press.
- Hewage, S.R.I., 2019. Erosion Potential of Pipe Embedment Materials Through Defective Sewer Pipes. Swinburne University of Technology, Melbourne.
- Horton, R., E., 1945. Erosional Development of Streams and Their Drainage Basins; Hydrophysical Approach to Quantitative Morphology. *Bulletin of the Geological Society of America*, 56, 275–370.
- Ibrahim, A. dan Meguid, M.A., 2023. CFD-DEM Simulation of Sand Erosion Into Defective Gravity Pipes Under Constant Groundwater Table. *Tunnelling and Underground Space Technology*, 131, 104823.
- Indiketiya, S., Jegatheesan, P., dan Rajeev, P., 2017. Evaluation of Defective Sewer Pipe Induced Internal Erosion and Associated Ground Deformation Using Laboratory Model Test. *Canadian Geotechnical Journal*, 42.
- Jafari, M., Tahmoures, M., Ehteram, M., Ghorbani, M., dan Panahi, F., 2022. *Soil Erosion Control in Drylands*. Switzerland: Springer International Publishing.
- Jung, B., Ryu, D.-W., dan Yum, B.W., 2023. Numerical simulation of urban road collapse induced by the damaged sewer pipe and repetitive heavy rainfalls. *Geosciences Journal*, 27 (4), 515–529.



- Krishna, P.L. dan Rajasekhar, D.K., 2018. Analysis and Design of Box Culvert. *International Journal of Science Technology & Engineering*, 4 (10), 141–156.
- Kuswari, S., 2024. Studi Eksperimental Pengaruh Celah Pada Sambungan Saluran Berbentuk Bulat. Thesis. Universitas Gadjah Mada, Yogyakarta.
- Kuswari, S., Hardiyatmo, H.C., dan Fathani, T.F., 2024. Effects of Gap on Erosion Surrounding Culvert Joints - An Experimental Study. *INERSIA Informasi dan Ekspose Hasil Riset Teknik Sipil dan Arsitektur*, 20 (2), 154–163.
- Kwak, T.-Y., Woo, S.-I., Chung, C.-K., dan Kim, J., 2020. Experimental assessment of the relationship between rainfall intensity and sinkholes caused by damaged sewer pipes. *Natural Hazards and Earth System Sciences*, 20 (12), 3343–3359.
- Li, X., Chen, R., Liu, L., Zhou, C., dan Bate, B., 2023. A non-Darcy flow CFD–DEM method for simulating ground collapse induced by leakage through underground pipeline defect. *Computers and Geotechnics*, 162, 105695.
- Morgan, R.P.C., 2005. *Soil Erosion and Conservation*. 3rd ed. Malden, MA: Blackwell Pub.
- Navab, R., 2014. Productivity Analysis of Closed Circuit Television (CCTV) Sewer Mainline Inspection. University of Alberta, Alberta.
- Propika, J., Lestari, L., dan Muti, J., 2018. The Use of Box Culvert Precast as a Main Bridge Structure in Arterial Highway Road: An Analysis Study. *IPTEK Journal of Proceedings Series*, 0 (6).
- Sari, N.F., Hardiyatmo, H.C., dan Fathani, T.F., 2025. Study on Erosion Mechanisms Caused by Leakage at Culvert Joints and Outlets. *SNTI*.
- Sato, M. dan Kuwano, R., 2015. Suffusion and Clogging by One-Dimensional Seepage Tests on Cohesive Soil. *Soils and Foundations*, 55 (6), 1427–1440.
- Sholeha, A., 2024. Studi Eksperimental Perilaku Erosi Akibat Variasi Lebar Celah dan Waktu pada Sambungan Saluran Drainase. Thesis. Universitas Gadjah Mada, Yogyakarta.
- Sholeha, A., Hardiyatmo, H.C., dan Ismanti, S., 2024. Pengaruh Lebar Celah Pada Erosi Disambungan Saluran Berbentuk Persegi. *SNTI*, 2.
- Suripin, 2004. *Sistem Drainase Perkotaan yang Berkelanjutan*. Yogyakarta: ANDI Offset.
- Tang, Y., Zhu, D.Z., dan Chan, D.H., 2017. Experimental Study on Submerged Sand Erosion through a Slot on a Defective Pipe. *Journal of Hydraulic Engineering*, 143 (9), 04017026.
- Tang, Y., Zhu, D.Z., Chan, D.H., dan Zhang, S., 2023. Physical and analytical modeling of soil loss caused by a defective sewer pipe with different defect locations. *Acta Geotechnica*, 18 (5), 2639–2659.
- Tian, Z., Yao, Q., Zhang, S., dan Qiao, N., 2022. Experimental Study on Levee Failure due to the Damage of Pressure less Culvert Pipe. Dipresentasikan pada International Conference on Mechanics and Civil Engineering, CSP.
- Tribun Pekanbaru, 2025. Jalan Lobak Amblas Usai Hujan Deras Guyur Kota Pekanbaru [online]. *Tribunpekanbaru.com*. Available from: https://pekanbaru.tribunnews.com/2025/04/05/jalan-lobak-amblas-usai-hujan-deras-guyur-kota-pekanbaru?lgn_method=google&google_btn=onetap [Diakses 10 Jul 2025].
- Wang, Z.-Y., Liu, J.-C., Tan, Y., dan Long, Y.-Y., 2025. Experimental and numerical investigation on internal erosion induced by infiltration of defective buried pipe. *Bulletin of Engineering Geology and the Environment*, 84 (1), 38.
- Xu, J., Wang, F., dan Vaughan, B., 2025. CFD–DEM Analysis of Internal Soil Erosion Induced by Infiltration into Defective Buried Pipes. *Geosciences*, 15 (7), 253.



Studi Eksperimental Erosi Akibat Kebocoran di Sekitar Sambungan dan Outlet pada Saluran Gorong-Gorong Persegi

Wan Muhammad Akbar, Prof. Dr. Ir. Hary Christady Hardiyatmo, M.Eng., DEA ; Dr. Eng. Ir. Fikri Faris, S.T., M.Eng

Universitas Gadjah Mada, 2025 | Diunduh dari <http://etd.repository.ugm.ac.id/>

UNIVERSITAS
GADJAH MADA

- Ye, X., Zuo, J., Li, R., Wang, Y., Gan, L., Yu, Z., dan Hu, X., 2019. Diagnosis of Sewer Pipe Defects on Image Recognition of Multi-Features and Support Vector Machine in a Southern Chinese City. *Frontiers of Environmental Science & Engineering*, 13 (2), 17.
- Zhang, D.-M., Du, W.-W., Peng, M.-Z., Feng, S.-J., dan Li, Z.-L., 2020. Experimental and numerical study of internal erosion around submerged defective pipe. *Tunnelling and Underground Space Technology*, 97, 103256.
- Zumrawi, M.M.E., 2014. The Impacts of Poor Drainage on Road Performance in Khartoum, 3 (1), 901–907.