

DAFTAR PUSTAKA

- Badan Pusat Statistik. (2023). *Statistik Produksi Dan Ekspor Batu Bara Indonesia 2023*. Diakses dari: <https://www.bps.go.id>.
- Blanchard, B. S. (2004). *Logistics engineering and management* (6th ed.). Prentice Hall.
- Devaraju, A. (2015). *A Critical Review on Different Types of Wear of Materials*, International Journal of Mechanical Engineering and Technology (IJMET), 6(11), 77-83.
- Gaspari, P., & Rossi, T. (2020). *Root cause analysis using fishbone diagram for quality improvement in manufacturing*. Journal of Quality Engineering, 32(4), 456-472.
- Gaspersz, V. (2002). *Total Quality Management*. Jakarta: Gramedia Pustaka Utama.
- Gazali, S. T. (2023). *Clutch Control System Scania Truck*. Diakses dari: <https://www.scribd.com/document/666719038/CLUTCH-CONTROL-SYSTEM-SCANIA-TRUCK>.
- Haksa, M., & Ariandi, R. (2025). *Analisis pengaruh siklus operasi terhadap laju kerusakan komponen transmisi heavy equipment*. Jurnal Teknik Mesin Indonesia, 12(2), 115-125.
- Hu, C., Geng, G., Liu, X., Yang, S., & Tang, X. (2023). *Dynamic Characteristics of the Multistage Planetary Gear Transmission System Based on A Stochastic Load*. International Journal of Precision Engineering and Manufacturing, 24, 657–669. DOI: 10.1007/s12541-022-00743-x.
- Ismoyo, I. S. B. (2022). *Analisa Kerusakan “Premature Failure” pada Komponen Transmisi HD785-7 di PT. XYZ*. Universitas Kristen Indonesia.
- ISO 4406. (1999). *Hydraulic fluid power—contamination control and fluid cleanliness codes*. International Organization for Standardization.
- Li, Z., Chen, Z., Guo, L., & Zhai, W. (2025). *Nonlinear Dynamics of Gear Transmission With an Improved Wear Model*. International Journal of

- Mechanical Sciences, 245, 110399. DOI: 10.1016/j.ijmecs.2025.110399.
- Mahmood, A., Ahmadi, A., Verma, A. K., Srividya, A., & Kumar, U. (2013). *Fuzzy fault tree analysis: A review of concept and application*. International Journal of System Assurance Engineering and Management, 4(1), 19–32. <https://doi.org/10.1007/s13198-013-0145-x>
- Margono, K.T., (2021). *Analisis Permasalahan Pada Pelumasan Dengan Standar Kowa (Komatsu Oil Wear Analysis)*. United Tractors.
- Maulana, E. (2018). *Analisa Kerusakan Sistem Transmisi Pada Wheel Loader Shantui SL30W*. Universitas Muhammadiyah Surakarta.
- Prasetyo, A., & Hidayat, R. (2019). *Analisis Dampak Keterlambatan Pemeliharaan Mesin Terhadap Efisiensi Produksi*. Jurnal Teknik Industri, 20(3), 145-152.
- PT Trakindo. (2011). *Applied Failure Analysis Buku Panduan Siswa*. Cilengsi: Training Center PT Trakindo Utama.
- PT United Tractors Tbk. (2006). *Perawatan/ Maintenance*. Technical Training Department.
- Raharja, B. S., Sufiyanto, S., & Sunada, I. M. (2018). *Analisa Keausan Roda Gigi Lurus Secara Mikroskopik Dengan Variasi Beban*. Jurnal Teknik Mesin Transmisi, 14(2), 299–305. DOI: 10.26905/jtmt.v14i2.4656.
- Rausand, M., & Hoyland, A. (2004). *System reliability theory: Models, statistical methods, and applications* (2nd ed.). Wiley-Interscience.
- Rizaldy, N. D., Vitalaya, A. I. (2020). *Analisis Kegagalan Mekanik LO Clutch*. Jurnal Inovisi, 16(2), 72-78.
- Santoso & Prasetyo, Sandi Danu. (2025). *Analisis Kegagalan Mesin Chemical Sheet Menggunakan Metode Root Cause Analysis (RCA) di PT.XYZ*. Jurnal Multidisiplin Saintek, 9(7), 1-16. DOI: 10.8734/Kohesi.v1i2.365
- Sari, D., Hidayat, R., & Prasetyo, A. (2021). *Analisa penyebab kerusakan sistem kerja transmisi pada unit Reach Stacker Kalmar 455*. Prosiding Seminar Teknik Industri, 5(1), 45–53.
- Scania CV AB. (2011). *Scania Diagnos & Programmer 3 (SDP3)*.
- Scott, D., & McNab, D. (2016). *Surface Mining Equipment*. SME Mining

Engineering Handbook (3rd ed., pp. 1001–1025). Society for Mining, Metallurgy, and Exploration.

Supriyanto, A., Alimuddin, & Bohari. (2018). *Analisis Logam Fe, Cu, Pb, dan Zn dalam Minyak Pelumas Baru dan Bekas Menggunakan X-Ray Fluorescence*. *Jurnal Atomik*, 3(1), 13-17.

Totten, G. E. (2017). *Handbook of lubrication and tribology: Volume I: Application and maintenance* (2nd ed.). CRC Press.

Utomo, B., & Sulistyanto, H. (2022). *Analisa Kerusakan dan Perbaikan Transmisi Low Power Wheel Loader XCMG ZL50GN*. *Jurnal Teknik Mesin*, 12(2), 78–85.

Wolak, A., Zając, G., & Słowik, T. (2021). *Measuring Kinematic Viscosity of Engine Oils: A Comparison of Data Obtained From Four Different Devices*. *Sensors*, 21(7), 2530. DOI: 10.3390/s21072530.