UNIVERSITAS
GADJAH MADA
Analisis Kualitas Isolasi Stator Generator 353 MVA Unit 20 PLTU Rembang Menggunakan Metode Electrical Assessment pada Overhaul Medium Inspection
Raihan Ulwan Fajar, Ir. Lukman Subekti, M.T., IPM
Universitas Gadjah Mada, 2026 | Diunduh dari http://etd.repository.ugm.ac.id/

DAFTAR PUSTAKA

[1] Badan Pusat Statistik, "Listrik yang Didistribusikan Menurut Provinsi (GWh)," [Online]. Available: https://www.bps.go.id/id/statistics-table/2/ODU5IzI=/listrik-yang-didistribusikan-menurut-provinsi-gwh-.html, 2025, accessed: Jun. 7, 2026.

[2] International Energy Agency, *Electricity Market Report*. Paris, France: IEA, 2023.

[3] A. Belhaouzi, M. Ouassaid, and H. Sabir, "Diagnostic and Monitoring Methods for Large Synchronous Machines: A Comprehensive Review of Failure Mechanisms, Condition Monitoring Signals, and Fault Diagnosis Techniques," *Results in Engineering*, vol. 29, 2026.

[4] G. C. Stone, E. A. Boulter, I. Culbert, and H. Dhirani, *Electrical Insulation for Rotating Machines: Design, Evaluation, Aging, Testing, and Repair*. Piscataway, NJ, USA: IEEE Press, 2004.

[5] IEEE Instrumentation and Measurement Society, "IEEE Std 62.2-2004: IEEE Guide for Diagnostic Field Testing of Electric Power Apparatus—Electrical Machinery," IEEE Standard, New York, NY, USA, 2004.

[6] Dongfang Electric Corporation Limited, *Operation & Maintenance Manual: Dongfang 300MW Steam Turbine Generator Unit*, Dongfang Electric Corporation Limited, Chengdu, China, September 2013, draft Version.

[7] G. Wijoyo, "Justifikasi Overhaul Simple Inspection (SI)/Minor untuk Meningkatkan Equivalen Availability Factor (EAF) PT Pembangkit Listrik XYZ, Studi Kasus pada Steam Turbine 1.0 (ST 1.0)," Master's thesis, Institut Teknologi Sepuluh Nopember, Surabaya, Indonesia, 2019.

[8] A. Gunawan, "Analisis Hasil Pengujian Tan Delta Stator Generator Setelah Overhaul Menggunakan Omicron CPC 100 dan CP-TD1 di PLTU Sumber Alam Sekurau Tanjung Selor," Semarang, Indonesia, 2024.

[9] M. H. H. A. Majid, N. H. Nik Ali, N. M. Samsuddin, M. H. F. Rahiman, and A. S. A. Rahman, "Comprehensive Evaluation of Generator Insulation Health: Electrical Testing Techniques," in *Proc. IEEE Control and System Graduate Research Colloquium (ICSGRC)*. IEEE, 2024.

UNIVERSITAS
GADJAH MADA
Analisis Kualitas Isolasi Stator Generator 353 MVA Unit 20 PLTU Rembang Menggunakan Metode Electrical Assessment pada Overhaul Medium Inspection
Raihan Ulwan Fajar, Ir. Lukman Subekti, M.T., IPM
Universitas Gadjah Mada, 2026 | Diunduh dari http://etd.repository.ugm.ac.id/

[10] N. Pattanadech and S. Jeenmuang, "Condition Assessment of Rotating Machine Insulation: Case Studies from Power Plants," in *Proc. Int. Conf. on Diagnostics in Electrical Engineering (Diagnostika)*. IEEE, 2024.

[11] L. S. Mahendra, Zulkifli, B. Herwono, Y. Anggraini, E. N. Solikhah, and K. Nisa, "Analisis Kondisi Belitan Stator Generator Melalui Pengujian Indeks Polarisasi dan Tan Delta (Dissipation Factor)," *Jurnal Teknik Elektro dan Komputasi (ELKOM)*, 2023.

[12] T. Chopel and T. Suwanasari, "Condition Assessment of Generator Insulation Using Diagnostic Tests," in *Proc. IEEE Conf.*, 2019.

[13] G. Klempner and I. Kerszenbaum, *Operation and Maintenance of Large Turbo Generators*. Hoboken, NJ, USA: John Wiley & Sons, 2004.

[14] S. J. Chapman, *Electric Machinery Fundamentals*, 4th ed. New York, NY, USA: McGraw-Hill, 2004.

[15] IEEE Power and Energy Society, "IEEE Std 1110-2019 (Revision of IEEE Std 1110-2002): IEEE Guide for Synchronous Generator Modeling Practices and Parameter Verification with Applications in Power System Stability Analyses," IEEE Standard, New York, NY, USA, 2020.

[16] KJ Dynatech Inc., "Online Partial Discharge Diagnosis," [Online]. Available: http://www.kjdyna.com/skin/page/page3_sub04.html, Seoul, Korea, accessed: Jun. 17, 2026.

[17] Admin, "Difference between Cylindrical and Salient Pole Rotor Synchronous Generator," [Online]. Available: https://electricalbaba.com/difference-between-cylindrical-and-salient-pole-rotor-synchronous-generator/, 2018, accessed: Jun. 17, 2026.

[18] L. L. Grigsby, Ed., *The Electric Power Engineering Handbook*, ser. The Electrical Engineering Handbook Series. Boca Raton, FL, USA: CRC Press, 2001.

[19] International Electrotechnical Commission, "IEC 60085:2007: Electrical Insulation – Thermal Evaluation and Designation," International Standard, Geneva, Switzerland, 2007.

[20] IEEE Power and Energy Society, "IEEE Std 43-2013: IEEE Recommended Practice for Testing Insulation Resistance of Electric Machinery," IEEE Standard, New York, NY, USA, 2013.

UNIVERSITAS
GADJAH MADA
Analisis Kualitas Isolasi Stator Generator 353 MVA Unit 20 PLTU Rembang Menggunakan Metode Electrical Assessment pada Overhaul Medium Inspection
Raihan Ulwan Fajar, Ir. Lukman Subekti, M.T., IPM
Universitas Gadjah Mada, 2026 | Diunduh dari http://etd.repository.ugm.ac.id/

[21] Megger, "A Guide to Diagnostic Insulation Testing Above 1 kV," Technical Guide, Dallas, TX, USA, 2018.

[22] K. Suzuki, H. Sako, S. Maeda, and K. Mio, "Temperature Dependence of Insulation Resistance and Current Components for Generator Stator Bars," in *Proc. IEEE Electrical Insulation Conf. (EIC)*, Montréal, QC, Canada, 2016, pp. 452–455.

[23] IEEE Power and Energy Society, "IEEE Std 286-2024: IEEE Recommended Practice for Measurement of Power Factor Tip-Up of Electric Machinery Stator Coil Insulation," IEEE Standard, New York, NY, USA, 2024.

[24] Verband Deutscher Elektrotechniker, "VDE 0530 Bagian 1: Mesin Listrik Berputar – Data Desain dan Mode Operasi (Peringkat dan Kinerja)," German Standard, Frankfurt, Germany, Jul. 1991.

[25] International Electrotechnical Commission, "IEC/TS 60034-27:2006: Rotating Electrical Machines – Part 27: Off-line Partial Discharge Measurements on the Stator Winding Insulation of Rotating Electrical Machines," Technical Specification, Geneva, Switzerland, 2006.

[26] G. C. Stone, A. Cavallini, G. Behrmann, and C. A. Serafino, *Practical Partial Discharge Measurement on Electrical Equipment*. Hoboken, NJ, USA: IEEE Press/John Wiley & Sons, 2023.

[27] F. Oettl, M. Krueger, W. Koltunowicz, L.-V. Badicu, and B. Gorgan, "Partial Discharge Measurements on Rotating Machines – Experience and Innovation," *OMICRON Technical Article*, 2017.

[28] OMICRON, "Partial Discharge Measurement on Rotating Machines," OMICRON Electronics GmbH, Klaus, Austria, Technical Article, 2020.

[29] Iris Power Engineering, "Partial Discharge Interpretation Guidelines for Rotating Machine Stator Windings," Iris Power – Qualitrol, Toronto, ON, Canada, Technical Reference Manual, 2019.