



## ABSTRACT

Streetscape in Pasar Gede heritage area in Surakarta is important to be preserved due to its physical and non-physical uniqueness. Meanwhile, the development of Pasar Gede area for commercial activities causes changes that if not controlled will reduce the quality of existing streetscape. Therefore, the visual quality of streetscape in Pasar Gede area becomes important to be studied further. This study aims to assess the visual quality of streetscape in Pasar Gede area and to determine the factors that influence it. The components of visual quality that are assessed in this study comprise vividness, intactness, and unity. Those components are assessed through scoring method on each segment of street space. Furthermore, the assessment results are used to determine how streetscape components such as building facades, vegetation, vehicle paths, pedestrian paths and street furniture affect the level of visual quality in Pasar Gede area. The results indicate that the visual quality of streetscape in Pasar Gede area is in fair level (3,54 on a scale of 5) with building facade as the most influential streetscape component.

**Keywords:** visual quality, streetscape, pasar gede, surakarta



## INTISARI

*Streetscape* di kawasan warisan Pasar Gede, Surakarta penting untuk dilestarikan karena keunikan aspek fisik dan non fisiknya. Sementara itu, pengembangan kawasan Pasar Gede untuk kegiatan komersial menyebabkan perubahan yang jika tidak dikendalikan akan mengurangi kualitas *streetscape* yang ada. Oleh karena itu, kualitas visual *streetscape* di kawasan Pasar Gede menjadi penting untuk dikaji lebih lanjut. Penelitian ini bertujuan untuk menilai kualitas visual *streetscape* di kawasan Pasar Gede dan untuk mengetahui faktor-faktor yang mempengaruhinya. Komponen kualitas visual yang dinilai dalam penelitian ini terdiri dari kejelasan, keutuhan, dan kesatuan. Komponen-komponen tersebut dinilai melalui metode *scoring* pada setiap segmen ruang jalan. Selanjutnya, hasil penilaian digunakan untuk menentukan bagaimana komponen *streetscape* seperti fasad bangunan, vegetasi, jalur kendaraan, jalur pejalan kaki dan street furniture mempengaruhi tingkat kualitas visual di kawasan Pasar Gede. Hasil penelitian ini menunjukkan bahwa kualitas visual *streetscape* di kawasan Pasar Gede berada pada keadaan cukup baik (3,54 pada skala 5) dengan fasad bangunan sebagai komponen *streetscape* yang paling berpengaruh.

**Kata kunci** : kualitas visual, *streetscape*, pasar gede, surakarta