

DAFTAR ISI

HALAMAN SAMBUNG	i
LEMBAR NOMOR PERSOALAN.....	ii
LEMBAR PENGESAHAN.....	iii
LEMBAR PERNYATAAN	iv
MOTTO	v
LEMBAR PERSEMBAHAN.....	vi
KATA PENGANTAR	vii
INTISARI.....	ix
<i>ABSTRACT</i>	x
DAFTAR ISI.....	xi
DAFTAR GAMBAR.....	xv
DAFTAR TABEL	xviii
BAB I PENDAHULUAN	
1.1 Latar Belakang Masalah	1
1.2 Rumusan Masalah.....	4
1.3 Batasan Masalah	4
1.4 Tujuan Penelitian	5
1.5 Manfaat Penelitian	5
1.6 Sistematika Penulisan.....	6
BAB 2 TINJAUAN PUSTAKA DAN DASAR TEORI	
2.1 Tinjauan Pustaka.....	7
2.2 Dasar Teori	8
2.2.1 Dump Truck Komatsu HD785-7	8
2.2.2 <i>Engine Diesel</i>	10
2.2.2.1 Siklus Ideal <i>Engine Diesel</i>	11
2.2.2.2 Siklus Aktual <i>Engine Diesel</i>	14
2.2.2.3 Bahan Bakar <i>Engine Diesel</i>	14
2.2.2.4 Teori Pembakaran.....	15
2.2.2.5 Reaksi Pembakaran.....	16
2.2.3 Pelumasan <i>Engine Diesel</i>	17

2.2.3.1 Pengertian Pelumasan	17
2.2.3.2 Fungsi Pelumasan	18
2.2.3.3 Bahan Pelumas	19
2.2.3.4 Jenis-Jenis Pelumasan	22
2.2.3.5 Sifat Pelumas.....	23
2.2.3.6 Klasifikasi Minyak Pelumas	25
2.2.4 Analisa Pelumas	28
2.2.5 Tujuan dan Ruang Lingkup Analisa Pelumas	31
2.2.6 Program Pemeriksaan Mesin (PPM)	33
2.2.7 <i>Vehicle Health Monitoring System</i> (VHMS)	33
2.2.8 <i>Dyno Test</i>	33
2.2.9 <i>Inner Part</i>	33
2.2.10 Friksi (<i>Friction</i>)	37
2.2.11 Keausan (<i>Wear</i>).....	38
BAB 3 METODE PENELITIAN	
3.1 Lokasi dan Waktu Penelitian	44
3.2 Bahan Penelitian	44
3.3 Alat Penelitian.....	44
3.3.1 Alat Utama	44
3.3.2 Alat Pendukung	45
3.4 Pelaksanaan Penelitian	46
3.4.1 Proses Persiapan	47
3.4.2 Proses Pengambilan Sampel Pelumas	47
3.4.3 Proses Pengambilan Data VHMS dan Program Pemeriksaan Mesin	49
3.4.4 Proses <i>Engine Overhaul</i>	50
3.4.5 Tahap <i>Dyno Test</i>	51
3.5 Tahap Pengelompokan Data	51
3.6 Tahap Analisis Hasil	52
3.7 Analisis Hasil.....	53

BAB 4 ANALISA DAN PEMBAHASAN

4.1 Analisa Pelumas dan Keausan	54
4.1.1 Analisa Kandungan <i>Wear Metal</i>	57
4.1.2 Analisa Kandungan <i>Contaminants</i>	58
4.1.3 Analisa <i>Infra Red</i>	59
4.1.4 Analisa <i>Physical Test</i> dan <i>viscosity oil</i>	60
4.1.5 Analisa Keausan <i>Inner Part</i>	61
4.1.5.1 Keausan <i>Cylinder Liner</i>	62
4.1.5.2 Keausan <i>Ring Piston</i>	65
4.1.5.3 Keausan <i>Piston</i> dan <i>Hole Piston</i>	69
4.1.5.4 Keausan <i>Pin Piston</i>	73
4.1.5.5 Keausan <i>Connecting Rod</i>	75
4.1.5.6 Keausan <i>Pin Metal</i>	79
4.1.5.7 Keausan <i>Crankshaft</i>	80
4.1.5.8 Keausan <i>Main Metal</i>	84
4.1.5.9 Keausan <i>Camshaft</i>	85
4.2 <i>Vehicle Health Monitoring System</i>	88
4.2.1 Analisa <i>Engine Speed</i>	88
4.2.2 Analisa <i>Blowby Engine</i>	89
4.2.3 Analisa <i>Engine Oil Pressure Low Idle</i>	90
4.2.4 Analisa <i>Engine Oil Pressure High Idle</i>	91
4.2.5 Analisa <i>Exhaust Temperature</i>	92
4.2.6 Analisa <i>Fuel rate</i>	92
4.2.7 Analisa <i>Coolant Temperature</i>	93
4.3 Analisa Perbandingan Performa Mesin	94
4.3.1 Analisa Program Pemeriksaan Mesin (PPM)	94
4.3.2 Analisa <i>Dyno Test</i>	96

BAB 5 PENUTUP

5.1 Kesimpulan	100
5.2 Saran	100
DAFTAR PUSTAKA.....	100
LAMPIRAN	101

DAFTAR GAMBAR

Gambar 1.1 Populasi Unit PT SIS Site Admo	3
Gambar 2.1 <i>Dump Truck</i> Komatsu HD785-7	8
Gambar 2.2 Siklus Mesin 4 Langkah	11
Gambar 2.3 Posisi Pergerakan <i>piston</i>	12
Gambar 2.4 Diagram P-v siklus ideal diesel	13
Gambar 2.5 Siklus Aktual Motor Diesel 4 Langkah.....	14
Gambar 2.6 Proses Pembakaran <i>Engine diesel</i>	16
Gambar 2.7 <i>Cylinder liner</i>	33
Gambar 2.8 <i>Piston</i> dan <i>Connecting Rod</i>	35
Gambar 2.9 <i>Crankshaft</i>	36
Gambar 2.10 <i>Camshaft</i>	37
Gambar 2.11 <i>Adhesive wear</i>	39
Gambar 2.12 <i>Abrasive wear</i>	40
Gambar 2.13 <i>Corrosive wear</i>	41
Gambar 2.14 <i>Surface fatigue wear</i>	42
Gambar 2.15 <i>Fatigue wear</i>	43
Gambar 3.1 <i>Flow Chart</i>	56
Gambar 4.1 <i>Trend Wear Metal</i>	57
Gambar 4.2 <i>Trend Contaminants</i>	58
Gambar 4.3 <i>Trend Infra Red</i>	59
Gambar 4.4 <i>Trend Physical Test</i>	60
Gambar 4.5 <i>Viscosity Oil</i>	60
Gambar 4.6 Bagian pengukuran <i>cylinder liner</i>	62
Gambar 4.7 <i>Standart size cylinder liner</i>	63
Gambar 4.8 <i>Cylinder liner scratch</i>	64
Gambar 4.9 Keausan <i>cylinder liner</i>	64
Gambar 4.10 Bagian pengukuran lebar <i>ring piston</i>	66
Gambar 4.11 Bagian pengukuran <i>piston</i>	69
Gambar 4.12 Keausan <i>piston</i>	71

Gambar 4.13 Bagian pengukuran <i>inside diameter of piston pin</i>	72
Gambar 4.14 <i>Standart size inside diameter of piston pin</i>	72
Gambar 4.15 Bagian pengukuran <i>piston pin</i>	73
Gambar 4.16 <i>Standart size pin piston</i>	73
Gambar 4.17 <i>Pin piston</i>	75
Gambar 4.18 Bagian pengukuran <i>small end connecting rod</i>	75
Gambar 4.19 <i>Standart size connecting rod</i>	76
Gambar 4.20 Bagian pengukuran <i>big end connecting rod</i>	77
Gambar 4.21 <i>Standart size bearing metal</i>	79
Gambar 4.22 Bagian pengukuran keausan <i>pin metal</i>	80
Gambar 4.23 Bagian pengukuran <i>pin Journal Crankshaft</i>	80
Gambar 4.24 <i>Standart size pin journal dan main journal crankshaft</i>	81
Gambar 4.25 Bagian pengukuran <i>main journal crankshaft</i>	81
Gambar 4.26 <i>Pin journal</i>	82
Gambar 4.27 <i>Main journal</i>	83
Gambar 4.28 Bagian pengukuran <i>main metal</i>	84
Gambar 4.29 <i>Main metal</i>	85
Gambar 4.30 Bagian pengukuran <i>camshaft</i>	85
Gambar 4.31 <i>Standart size camshaft</i>	86
Gambar 4.32 <i>Camshaft journal</i>	87
Gambar 4.33 <i>VHMS engine speed</i>	89
Gambar 4.34 <i>VHMS blowby engine</i>	89
Gambar 4.35 Ruang bakar.....	89
Gambar 4.36 <i>Cylinder head</i>	90
Gambar 4.37 <i>VHMS Engine oil pressure low idle</i>	90
Gambar 4.38 <i>VHMS Engine oil pressure high idle</i>	91
Gambar 4.39 <i>VHMS Engine exhaust temperature</i>	92
Gambar 4.40 <i>Engine fuel rate</i>	92
Gambar 4.41 <i>Engine coolant temperature</i>	93
Gambar 4.42 Data PPM.....	94
Gambar 4.43 Data PPM terakhir.....	95

Gambar 4.44 <i>Maintenance standart</i>	96
Gambar 4.45 <i>Recheck valve after load</i>	96
Gambar 4.46 <i>Performance spreadsheet</i>	97
Gambar 4.47 <i>Performance graph</i>	97
Gambar 4.48 <i>Sensor spreadsheet</i>	98
Gambar 4.49 <i>Sensor graph</i>	98
Gambar 4.50 <i>Evaluasi performa engine</i>	99

DAFTAR TABEL

Tabel 2.1 Arti <i>engine</i> SAA12V140E-3	9
Tabel 2.1 Spesifikasi <i>engine</i> SAA12V140E-3.....	9
Tabel 2.3 Standart mutu bahan bakar diesel	15
Tabel 3.1 Spesifikasi <i>Engine</i>	44
Tabel 4.1 <i>Typical Characteristics</i>	55
Tabel 4.2 Data Program Analisa Pelumas (PAP).....	56
Tabel 4.3 Hasil pengukuran keausan <i>cylinder liner</i>	62
Tabel 4.4 Data pengukuran keausan <i>top ring piston</i>	65
Tabel 4.5 Data pengukuran keausan <i>second ring piston</i>	67
Tabel 4.6 Data pengukuran keausan <i>oil ring piston</i>	68
Tabel 4.7 Data pengukuran keausan <i>piston</i>	70
Tabel 4.8 Data pengukuran <i>inside diameter of piston pin</i>	72
Tabel 4.9 Data pengukuran keausan <i>pin piston</i>	74
Tabel 4.10 Data pengukuran keausan <i>small end connecting rod</i>	76
Tabel 4.11 Data pengukuran keausan <i>big end connecting rod</i>	78
Tabel 4.12 Data pengukuran keausan <i>pin metal</i>	79
Tabel 4.13 Data pengukuran keausan <i>pin journal</i>	81
Tabel 4.14 Data pengukuran keausan <i>main journal</i>	82
Tabel 4.15 Data pengukuran keausan <i>main metal</i>	84
Tabel 4.16 Data pengukuran keausan <i>camshaft</i>	86