

## DAFTAR PUSTAKA

- API, 2010, *API Standart 610 Centrifugal Pumps for Petroleum, Petrochemical and Natural Gas Industries*, Washington.
- Askeland, D. R., Fulay, P. P., Wright, W. J., 2010, *The Science and Engineering of Materials, Sixth Edition*, Cengage Learning, USA.
- ASM, 1987, *ASM Handbook Vol. 12: Fractography*, ASM International.
- ASM, 2004, *ASM Handbook Vol. 9: Metallography and Microstructure*, ASM International.
- ASTM, 2015, *Designation: E8/E8M, Standard Test Methods for Tension Testing of Metallic Materials*, ASTM Internasional.
- ASTM, 2004, *Handbook of Comparative World Steel Standards, Third Edition*, ASTM Data Series Publication, USA.
- Bhandari, V. B., 2010, *Design of Machine Elements, Third Edition*, McGraw-Hill, USA.
- Bloch, H. P. dan Geitner, F. K., 1999, *Machinery Failure Analysis and Troubleshooting*, Gulf Professional Publishing, Houston.
- Callister, W. D., 2007, *Materials Science and Engineering an Introduction, Seventh Edition*, John Wiley & Sons Inc., USA.
- Dietzel, Fritz, 1996, *Turbin, Pompa, dan Kompresor alih bahasa Dakso Sriyono*, Penerbit Erlangga, Jakarta.
- Farag, M. M., 2008, *Materials and Process Selection for Engineering Design, Second Edition*, CRC Press, USA.
- Gere, J.M., 2004, *Mechanics of Materials, Sixth Edition*, Thomson Learning, Inc., USA
- Girdhar, Paresh dan Moniz, Octo, 2005, *Practical Centrifugal Pumps Design, Operation and Maintenance*, Elsevier, Burlington.
- Ghosh, D, Roy, H., Mondal, A, 2014, *Failure Investigation of Condensate Pump Shaft*, Journal of Failure Analysis and Prevention, August 2014, 450-453, DOI: 10.1007/s11668-014-9845-z.

- Haryadi, G. D., Pertiwanda, Suluh, Ismail, Rifky, 2017, Failure Analysis on Shaft of Circulating Water Pump at Power Plant, *Prosiding SNTTM XVI*, Oktober 2017, 32-37.
- JIS Handbook, 1981, *Ferrous Materials and Metalurgy*, Japanese Standards Association.
- Outokompu, 2013, *Handbook of Stainless Steel*, Outokumpu Oyj, Finlandia.
- Peckner, Donald dan Bernstein, I. M., 1977, *Handbook of Stainless Steel*, McGraw-Hill, New York.
- Prasetyo, C. D., 2016, *Analisa Kegagalan Poros Low Pressure Boiler Feed Pump (LP BFP) Ditinjau dari Aspek Metalurgi*, Jurusan Teknik Mesin Fakultas Teknologi Industri Institut Teknologi Sepuluh Nopember, Surabaya.
- Setiawan, Angga dan Witantyo, 2016, Analisa Kegagalan Poros Pompa Centrifugal Multistage (GA101A) Sub Unit Sintesa Urea PT. Petrokimia Gresik, *Jurnal Teknik ITS Vol. 5*, No. 2, A667-A671.
- Supriyono dan Adjiantoro, Bintang, 2010, Analisa Kegagalan Poros Pompa Air Laut Pada Unit PLTU, *Jurnal Ilmiah Teknologi dan Rekayasa*, Vol. 15, No. 3, 149-158.
- Tawancy, H. M., Ul-Hamid, Anwar, Abbas, N. M, 2004, *Practical Engineering Failure Analysis*, King Fahd U. Petroleum/Mineral Research Institute Dhahran, Dhahran.